


#### US Army Corps of Engineers Construction Engineering Research Laboratories

# **Site Study for Proposed Landfarm**

#### Fort Benning, GA

by Diane K. Mann Marilyn M. Weiss Scott Twait



Soil contaminated with petroleum, oil, and lubricants (POL) is often a problem at U.S. Army installations because of underground storage tanks (USTs) of questionable integrity, equipment leaks, and spills during operations and training. Landfarming is a soil-treatment option that capitalizes on the use of bacteria, which are especially adept at mediating biodegradation of compounds common to petroleum fuels, as a way of cleaning the soil. Microbial decomposition of POL contaminants results in fertile, useable soil and reduces monitoring, maintenance, and cost of landfilling.

Fort Benning has been exploring the feasibility of a landfarm as a proactive technology to assure preparedness for spills and leaks that contaminate soil with POL. Preliminary studies led to the selection of a prospective landfarm site. Detailed studies and hydrogeological modeling of the proposed landfarm site followed. This research verified the selected site's positive features for treating POL contaminated soil and explored weaknesses that designing would have to ameliorate.

DTIC QUALITY INSPECTED 2

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED

DO NOT RETURN IT TO THE ORIGINATOR

## **USER EVALUATION OF REPORT**

REFERENCE: USACERL Technical Report 97/136, Site Study for Proposed Landfarm: Fort Benning, GA

Please take a few minutes to answer the questions below, tear out this sheet, and return it to USACERL. As user of this report, your customer comments will provide USACERL with information essential for improving future reports.

1. repo	Does this report satisfy a need? (Comment on purpose, related project, or other area of interest for which ort will be used.)
2. pro	How, specifically, is the report being used? (Information source, design data or procedure, management cedure, source of ideas, etc.)
3. sav	Has the information in this report led to any quantitative savings as far as manhours/contract dollars ed, operating costs avoided, efficiencies achieved, etc.? If so, please elaborate.
-	
4.	What is your evaluation of this report in the following areas?
	a. Presentation:
	b. Completeness:
	c. Easy to Understand:
	d. Easy to Implement:
	e. Adequate Reference Material:
	f. Relates to Area of Interest:
	g. Did the report meet your expectations?
	h. Does the report raise unanswered questions?

	what you think should be changed to make this report and future reports eds, more usable, improve readability, etc.)
——————————————————————————————————————	ceus, more usable, improve readability, etc.)
-	•
5. If you would like to be contacted by discuss the topic, please fill in the following	the personnel who prepared this report to raise specific questions or wing information.
Name:	
Telephone Number:	
Organization Address:	
6. Please mail the completed form to:	
Department of	the Army

Department of the Army
CONSTRUCTION ENGINEERING RESEARCH LABORATORIES
ATTN: CECER-TR-I
P.O. Box 9005
Champaign, IL 61826-9005

# REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

AGENCY USE ONLY (Leave Blank)	2. REPORT DATE September 1997	3. REPORT TYPE AND DATES COVERED Final			
4. TITLE AND SUBTITLE Site Study for Proposed Landfa	5. FUNDING NUMBER MIPR 5FDPW100 YH6				
6. AUTHOR(S) Diane K. Mann, Marilyn M. W	eiss, and Scott Twait				
7. PERFORMING ORGANIZATION NAME(STATE OF CONSTRUCTION Engine P.O. Box 9005 Champaign, IL 61826-9005	s) AND ADDRESS(ES) eering Research Laboratories (US	SACERL)	8. PERFORMING OR REPORT NUMBER TR 97/136		
9. SPONSORING / MONITORING AGENCY Fort Benning Directorate of Pu ATTN: ATZB-PWN-P Bldg 6, Meloy Hall Fort Benning, GA 31905-5122	blic Works		10. SPONSORING / N AGENCY REPOR		
11. SUPPLEMENTARY NOTES  Copies are available from the N	National Technical Information Se	ervice, 5285 Port Royal	Road, Springfield	l, VA 22161.	
12a. DISTRIBUTION / AVAILABILITY STAT			12b. DISTRIBUTION	CODE	
underground storage tanks (US Landfarming is a soil-treatmen biodegradation of compounds contaminants results in fertile, Fort Benning has been exploring and leaks that contaminate soil studies and hydrogeological metals.	um, oil, and lubricants (POL) is of the control of questionable integrity, equationable integrity, equation that capitalizes on the use common to petroleum fuels, as a vuseable soil and reduces monitoring the feasibility of a landfarm as with POL. Preliminary studies le odeling of the proposed landfarm OL contaminated soil and explore	sipment leaks, and spills of bacteria, which are of way of cleaning the soil.  Ing, maintenance, and compare a proactive technology of to the selection of a prosite followed. This reserves.	especially adept a especially adept a . Microbial decom- ost of landfilling. to assure prepared rospective landfar earch verified the s	s and training.  It mediating  Inposition of POL  Inposition of POL	
				15. NUMBER OF PAGES	
14. SUBJECT TERMS petroleum, oil, and lubricant (I landfarming soil remediation	POL) biodegradation			130 16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICAT OF ABSTRACT Unclassifie		20. LIMITATION OF ABSTRACT SAR	

# **Executive Summary**

Soil contaminated with petroleum, oil, and lubricants (POL) is often a problem at U.S. Army installations because of underground storage tanks (USTs) of questionable integrity, equipment leaks, and spills during operations and training. Landfarming is a soil-treatment option that capitalizes on the use of bacteria, which are especially adept at mediating biodegradation of compounds common to petroleum fuels, as a way of "cleaning" the soil. Microbial decomposition of POL contaminants results in fertile, useable soil and reduces monitoring, maintenance, and cost of landfilling.

Fort Benning has been exploring the feasibility of a landfarm as a proactive technology to assure preparedness for spills and leaks that contaminate soil with POL. Preliminary studies led to the selection of a prospective landfarm site. Detailed studies and hydrogeological modeling of the proposed landfarm site followed. This research verified the selected site's positive features for treating POL contaminated soil and explored weaknesses that designing would have to ameliorate.

Because the landfarm site consists of typically permeable Coastal Plain sediments, the concern is possible mobilization of landfarm contaminants by infiltrating rainwater that might reach the water table in significant concentrations. Even poor quality soils similar to those at Fort Benning have the ability to greatly reduce petroleum concentration through retardation and biodegradation. However, to ensure no migration of even small amounts of contamination during extreme weather conditions, the landfarm design includes levees around the site, sloping of the site to a catchment basin, and a geosynthetic clay liner under the five treatment areas and a catchment basin. Clay is present in the soil at the site and a clay lens may underlie the site. The site is suitable for a landfarm because of its distance to groundwater and the slow speed at which contaminants would travel in the unsaturated zone.

Design for the proposed site includes five treatment areas of approximately 1 acre each with a total assimilative capacity of 119,790 lb

(almost 60 tons) per year for oily wastes at a 1 percent loading rate; the estimated yearly average of oily contaminate soil needing treatment at Fort Benning is 50 tons. The total area of the landfarm site encompasses approximately 20 acres, providing area for retention pond, buffer strips, building(s), equipment storage, and maneuvering space for equipment.

The life expectancy of landfarm is over 10 years (based on the landfarm established at Fort Polk in 1986 that is still operational). Design features, monitoring, and sound operation of the proposed Fort Benning Landfarm should ensure a life expectancy equal to or greater than the successful Fort Polk landfarm.

This study was conducted for Fort Benning Directorate of Public Works under Military Interdepartmental Purchase Request (MIPR) No. 5FDPW10048, Work Unit YH6, "Landfarm Technology at Fort Benning, GA." The technical monitor was Michael Nuckols, ATZB-PWN-P.

The work was performed by the Natural Resource Assessment and Management Division (LL-N) of the Land Management Laboratory (LL), U.S. Army Construction Engineering Research Laboratories (USACERL). The USACERL principal investigator was Dr. Diane K. Mann. At the time of this study, Marilyn K. Weiss and Scott Twait were graduate students at the University of Illinois, Champaign-Urbana. Some data from this report were developed as part of Masters theses research for Marilyn K. Weiss's A Hydrogeologic Assessment of a Proposed Landfarm Site at Fort Benning, Georgia, and Scott Twait's Subsurface Modeling of Fort Benning Landfarm Site. Dr. David J. Tazik is Acting Chief, CECER-LL-N; Dr. William D. Severinghaus is Operations Chief, CECER-LL; and William D. Goran, CECER-LL, is the responsible Technical Director. The USACERL technical editor was William J. Wolfe, Technical Resources.

COL James A. Walter is Commander and Dr. Michael J. O'Connor is Director of USACERL.

# **Contents**

SF	<sup>5</sup> 298	1
Exc	ecutive Summary	3
Fo	reword	5
1	Introduction	9
	Background	9
	Objectives	•
	Approach	
2	Master Plan	12
	Site Plan	12
	Site Research Data	15
	Environmental Characteristics	18
	Geological Characteristics of Coastal Plain	21
3	Site Modeling	28
	Field Data	28
	Groundwater Flow	29
	Numeric Groundwater Model	30
	Summary and Conclusions	35
4	Subsurface Modeling	37
	Field Data	37
	Modeling	37
5	Conclusion	40
Ref	ferences	42
App	pendix A: Loading Calculations	45
Арр	pendix B: Southeastern Coastal Plain Stratigraphic Correlation Chart	46
App	pendix C: Fort Benning Temperature, Wind Speed, and Humidity Data	48

Appendix D: Yearly Precipitation Totals for Fort Benning Georgia	49
Appendix E: Fort Benning Precipitation	50
Appendix F: Average Monthly Precipitation for Fort Benning, GA	51
Appendix G: Description of Water Quality Analysis	52
Appendix H: Water Quality Analysis	53
Appendix I: Background Water Quality From a Landfill North of Site	54
Appendix J: Water Analysis Scatter Diagram	56
Appendix K: Generalized Section, Muscogee to Randolph Counties	57
Appendix L: 1994/1995 Drilling Logs	58
Appendix M: Geologic Description of Borings	66
Appendix N: Grain Size Analysis	72
Appendix O: Hydraulic Conductivity Values	93
Appendix P: SCS Method of Abstractions	95
Appendix Q: Statistical Rainfall Intensity Data for Fort Benning	96
Appendix R: SCS Rainfall Distribution for 24-Hour StormStorm	97
Appendix S: Transient Model Results	98
Appendix T: Logging Data	100
Appendix U: Clay Layer	118
Appendix V: FEMWATER and LEWASTE Grid	119
Appendix W: Assumptions for Program Without Clay Liner	120
Appendix X: Assumptions for Program With Clay Liner	121
Appendix Y: LEWASTE Grids	122
Distribution	

# **List of Figures and Tables**

Figure	es	
1	Location of proposed landfarm site at Fort Benning, GA	1
2	Proposed landfarm site.	18
3	Location of site in relation to surface water and potable water sources	17
4	Fingerprint diagram comparing surface water sample and MW-1 sample	21
5	Idealized cross-section of groundwater flow patterns.	23
6	Topographic map of proposed landfarm region and location of borings	25
7	Representative graphic log of site stratigraphy.	27
8	Direction of groundwater flow for proposed landfarm region.	29
9	Discrete division of Harps Creek watershed for groundwater modeling	31
10	Potentiometric surface of the water table aquifer	33
11	Direction of groundwater flow in the water table aquifer.	34
Tables	<b>S</b>	
1	Soils typical of the site	26
2	Hydraulic head values for the steady state model	32
3	Sample test results	37

## 1 Introduction

#### **Background**

Fort Benning is located approximately 12.87 km (8 mi) south of the city of Columbus in the west-central part of Georgia with part of the reservation located across the Chattahoochee River which forms the Georgia-Alabama border. The military reservation is comprised of 181,835 acres; 169,679 acres are in Georgia in the counties of Chattahoochee and Muscogee and 12,156 acres are in Alabama in Russell county. Located on the northern edge of the Atlantic Coastal Plain, the predominantly rolling pine-covered surfaces are highest in the east, up 740 ft above sea level, and lowest in the southwest, about 190 ft above sea level along the Chattahoochee River.

Fort Benning has been exploring the feasibility of a landfarm as a proactive technology to assure preparedness for spills and leaks that contaminate soil with POL. Preliminary studies led to the selection of a prospective landfarm site. The proposed landfarm site, previously used as an Apari heliport, is southwest of the intersection of Jamestown Road and Eighth Division Road in the Harps Creek local drainage system (Figure 1). Further, more detailed studies and hydrogeological modeling of the proposed landfarm site were required.

## **Objectives**

This objective of this research was to verify the selected site's positive features for treating POL contaminated soil and to identify and explore weaknesses that would have to be ameliorated through design.

## **Approach**

- 1. A hydrologic assessment of the Fort Benning site was done.
- 2. A groundwater flow assessment was done via 2-dimensional modeling software.

- 3. Subsurface sampling was done to determine soil composition and characteristics by:
  - a. taking seven soil borings
  - b. converting four of the borings into monitoring wells.
- 4. The flow of water and contaminates through saturated and unsaturated soil layers was modeled via 2-dimensional computer modeling program.
- 5. Results of the modeling were analyzed and conclusions were drawn regarding the suitability of the Fort Benning site for a landfarm application.




Figure 1. Location of proposed landfarm site at Fort Benning, GA.

## 2 Master Plan

The proposed Fort Benning landfarm is within the boundaries of the military installation and is the property of the U.S. government (Figure 1). Currently used for storage of disabled military tanks, the former heliport is relatively flat, sparsely vegetated, surrounded by asphalt roads, and partially covered by steel lattice gridwork (landing mat).

#### Site Plan

The study included the area that could be incorporated into a landfarm approximately 20 acres, totally enclosed by levees (Figure 2). Of the 20 acres, approximately 6 acres in the northwest corner are designed for impounded runoff. The retention pond is designed to be 5-ft deep and sized to hold the runoff from a maximum 24-hour storm. Useable landfarm is divided into five separate treatment areas, arranged in order so that furrows would run perpendicular to the predominant slope (at a 2 to 3 percent grade). Each treatment area is about 300 X 150 ft (approximately 1 acre). A 300 X 30-ft grassy buffer strip between each treatment area is part of the design to further inhibit runoff. Total treatment area of 5 acres has an assimilative capacity of 119,790 lb (nearly 60 tons) per year for oily wastes at a 1 percent loading rate. The estimated yearly average of oily contaminated soil needing treatment is 50 tons. Some sludge will probably be mixed in with the oily soil to enhance the biodegradation process. The yearly estimated average of sludge generated at Fort Benning is 1,260,000 gal, but the amount incorporated into landfarm would depend on the amount of soil being treated and the proportion required for ideal Supporting calculations may be found in Appendix A. amounts of treated sewage sludge would also be applied.

The proposed landfarm site is within a significant recharge area (Davis et al. 1992) and a synthetic liner would be used that matches the impermability of 3 ft of smectite clay as a barrier, even though the DRASTIC index (141-181) (Allen et al. 1987; Trent 1992) for the landfarm site is within the zone of average susceptibility to groundwater pollutants. The State currently regulates only areas of greater susceptibility.







Figure 2. Proposed landfarm site.





#### Site Research Data

#### **Aquifers**

The RASA study (Renken et al. 1989; Miller and Renken 1988) divided the Coastal Plain into four major regional aquifer systems: Northern Atlantic Coastal Plain, Southeastern Coastal Plain, Floridian, and Gulf Coastal Plain The landfarm site is near the northern edge of the aquifer systems. Southeastern Coastal Plain aquifer system. This system stretches through parts of Mississippi, Alabama, Georgia, South Carolina, and the northern part of The RASA report analyzed the Coastal Plain formations from the perspective of hydraulically interconnected strata or hydrostratigraphic units rather than according to classical geological stratigraphic units due to their regional extent and poor correspondence with physical boundaries of rock-The Southeastern Coastal Plain stratigraphic and time-stratigraphic units. aquifer system was subdivided into seven regional hydrogeologic units; four aquifer units identified as A1 through A4 are separated by three confining units, C1 through C3 (Appendix B).

Units A3, C3, and A4 are most likely to exist at the study area. The A3 regional aquifer extends as a continuous unit from North Carolina to central Alabama with the updip limit of the aquifer occurring at or near the Fall Line. It includes Blufftown Sands through the upper part of the Eutaw Formation. The upper surface of the aquifer slopes gently toward the coast at a gradient of 2.84 to 3.79 m/km (15 to 20 ft/mi). Hydraulic conductivity of the water-bearing zones within the A3 aquifer diminishes at depth as sandy strata of this unit grade into calcareous shale and chalk. Permeable parts of the aquifer thin greatly seaward; however, in southeast Georgia, it grades into permeable limestone that is part of the Floridian aquifer system. In western Georgia, the aquifer consists of shallow marine to nonmarine, feldspathic and locally glauconitic quartz sand and gravel that is, in places, interbedded with ferruginous, kaolinitic, and carbonaceous clay.

The C3 confining unit consists of oxidized, nonmarine, sandy and silty clay in shallow-updip areas of South Carolina and northeastern Georgia, but in other areas grades into marginal marine and marine calcareous clay, shale, mudstone, marl, and chalk. In much of Georgia, the poorly permeable beds that form the unit are considered equivalent to the clays of the Eutaw Formation or lower part of Blufftown Formation. The unit consists of chalky, micaceous, calcareous

carbonaceous clay that is silty and sandy locally. Minor amounts of glauconite, phosphate, and chlorite are present locally.

The A4 aquifer unit regionally is the most extensive clastic aquifer of the southeastern United States Coastal Plain and extends from South Carolina through Mississippi. Strata of this unit are equivalent to Eutaw and upper part of Tuscaloosa Formation. The aquifer is comprised of sparsely fossiliferous greenish gray to yellowish brown, fine to coarse grained, glauconitic calcareous sand that is interbedded with gray micaceous shale. Minor constituents include volcanic ash (bentonite), siderite, pyrite, and lignite. The upper surface of A4 aquifer slopes gently seaward at a gradient of 2.84 to 5.68 m/km (15 to 30 ft/mi) in Georgia, northern Florida, South Carolina, and adjacent counties of North Carolina, but slopes more steeply in Alabama and Mississippi. Similar to A3, the updip limit marks the inner margin of Coastal Plain sediments.

Neither previous hydrogeologic studies at Fort Benning nor this field study encountered the C3 confining unit; instead, base studies show groundwater to be hydraulically connected throughout Upper Cretaceous deposits reaching a total thickness of about 28.5 m (750 ft). Water table conditions exist at Fort Benning, but farther south, groundwater is confined by poorly permeable units. Water from Cretaceous aquifers is generally soft, and contains small quantities of dissolved solids. Water quality varies somewhat throughout various formations with best quality water in Tuscaloosa strata. Silica, calcium, and sulfate content is greater in Eutaw and Blufftown strata. Iron also occurs at greater concentrations in these formations and pH is lower (about 5 as opposed to 7) in the Tuscaloosa Formation. Wells finished in the Blufftown and Eutaw Formation have yielded up to 700 gpm (2.65 m³/min). Tuscaloosa Formation wells have yields up to 400 gpm (1.5 m³/min) (Meckelnburg 1993).

Fort Benning obtains most of its water supply from a surface intake structure in the Upatoi River upgradient from the proposed landfarm site. Additionally, the base operates three groundwater wells that serve a population of 1 to 100 persons and range in depth from 61.0 to 164.6 m (200 to 540 ft), probably tapping sands of the A4 aquifer unit. Locations of these groundwater sources also are upgradient from Harps Creek and the landfarm site. No known regional water sources or water intake structures exist within 24.1 km (15 mi) downgradient of the site (Figure 3).




Figure 3. Location of site in relation to surface water and potable water sources.

#### Climate

Fort Benning has a humid, subtropical climate characterized by long hot summers and mild winters.

#### Drainage

The proposed landfarm site is on a local topographic high that is part of a broad upland ridge with a gentle zero to 5 percent slope and characterized as part of the low plains (Terrain Analysis Center 1976). Intermittent streams surround the site on three sides and are deeply incised with slopes that range from 10 to over 45 percent. Elevation across the site slopes from 139 m (456 ft) to 128 m (420 ft) above MSL. The site is in the headwaters of Harps Creek, approximately 20 m (65 ft) to 35 m (115 ft) above the nearest intermittent

stream bed. The intermittent streams become permanent downstream, where stream beds broaden out and become more swamp-like, especially during periods of heavy rainfall. Ephemeral streams at the top of the watershed direct run-off primarily to the southwest becoming permanent and combining with Mill Creek at Harps Pond. Combined drainage of Harps and Mill Creeks flows into Oswichee Creek and subsequently drains into the Chattahoochee River, which flows southeast through the western part of Fort Benning. Watershed for Harps Creek up to Harps Pond encompasses approximately 11.93 km² (4.59 sq mi) (Figure 3). Surface water eventually empties into the Gulf of Mexico.

Shallow groundwater at Fort Benning normally flows in the same direction as surface water (USATHAMA 1992). Northeast of the site lies a regional groundwater divide. The divide is mostly coincident to U.S. Interstate 27, which runs northwest to southeast. Running parallel to the highway is Ochillee creek to the east and a portion of the Chattahoochee River to the west. Waters that fall east of the highway drain into Ochillee Creek and waters that fall west of the highway drain south to Chattahoochee River through such creeks as McMurrin Branch, Harps Creek, Mill Creek, and Oswichee Creek.

U.S. Geological Survey records show that of the average 127 cm (50 in.) of rainfall received by the State of Georgia, 18 percent becomes runoff, 70 percent is lost to evaporation, and only 12 percent has the potential of entering into aquifer systems (Kundell 1978). Large evapo-transpiration losses are the primary factor influencing seasonal water table fluctuations in unconfined groundwater. Shallow groundwater levels within the root zone vary annually, rising when plants are dormant and falling during the growing season. However, water level fluctuations in deep unconfined aquifers are the result of seasonal recharge patterns and water withdrawal.

#### **Environmental Characteristics**

There are no known archeological sites, historical sites, designated wildlife management areas, habitat for endangered species, recreational areas, swamps, marshes, or other sensitive ecological areas within 1000 ft of the proposed landfarm site. Consequently, no protective measures for such occurrences are necessary.

#### Temperature

Climatological data has been recorded at Lawson Army Airfield 7 miles west of the landfarm site (Figure 1). The annual mean temperature is approximately 18.7 °C (64.9 °F). The maximum and minimum daily means for each month fluctuate with the season (Appendix C). During July, mean maximum and mean minimum temperatures are 32.8 °C (91.0 °F) and 21.3 °C (71.1 °F), respectively. Whereas for January, the mean maximum temperature is 15 °C (59 °F) and mean minimum is about 2.2 °C (36 °F) (USATHAMA 1992).

#### **Humidity**

The relative humidity ranges from a mean of 49 percent in April and May to a mean of 59 percent in January and July; the average relative humidity in midafternoon is 54 percent (Appendix C).

#### Rainfall

The annual average rainfall at Fort Benning is approximately 124 cm/yr (48.8 in/yr). Yearly totals for years 1960 through 1993 range from 36.04 to 67.50 in. (Appendix D). Rainfall distribution has major peaks in March and July with a secondary peak during winter months of November and December (Appendix E). Periods of least precipitation are usually during May or June and again in October. The maximum Fort Benning yearly precipitation within the last 30 years was 171.5 cm (67.50 in) and 163.5 cm (64.37 in) in 1979 and 1964, respectively. The U.S. Soil Conservation Service (SCS) recorded the heaviest 1-day rainfall for the period of 1951 to 1977 at 13.5 cm (5.32 in) on 3 August 1977 in Columbus, GA (Johnson 1983). Monthly summaries of rainfall intensity data for Fort Benning are presented in Appendix F.

#### Water Quality

Water quality analyses were performed (Appendix G) to characterize the groundwater present at the site. Results of these analyses exhibited small levels of specific conductance (Appendix H). Due to the direct relationship of specific conductance and dissolved solids concentrations (Hem 1985), small specific conductance indicates a diminished level of dissolved solids. Samples ranged in pH from 3.5 to almost 7. Chemical analysis of nearby groundwater (Appendix I), similarly found levels of small specific conductance and generally acidic water with pH values that ranged from 3.5 to 4.5 (Meckelnburg 1993). The acidic nature of the water probably is a natural occurrence related to acidic

soil and sediments of the Coastal Plain. Small levels of dissolved solids are typical of waters with a brief residence time in the ground. The site is within a natural recharge area, near a topographic high of the water watershed and only 762 to 914.4 m (2500 to 3000 ft) from a regional groundwater divide. Porosity and conductivity of the site's subsurface material allow precipitation to infiltrate quickly to the groundwater zone. Thus, the main source of groundwater in the study area is infiltrating rainwater and is consistent with the finding of small concentrations of dissolved solids.

A marked similarity is found in fingerprint diagrams (Brassington 1988) comparing samples from MW-1 and surface water (Figure 4). Though not identical, the differences are probably due to the different histories of subsurface interactions encountered by the two waters. Surface water is a product of groundwater baseflow mixed with direct run-off of rainwater that has no residence time in the groundwater reservoir and only short contact with soil or vegetation. This causes surface samples from flowing streams to have a similar composition as rainwater with little dissolved solids. The small dissolved solids content of surface water is to be expected when groundwater also has little dissolved solids content. Lack of any one dominant anion or group of anions indicates a strong connection between groundwater and surface water at the site. In addition, all water samples, except for BH-4, had similar concentration of chloride, a conservative ion that moves through both soil and water with minimal retardation.

Scatter diagrams that plot various ion concentrations versus total dissolved solids, illustrate that waters of both subsurface and surface are related strongly to rainwater, except for samples BH-2 and BH-4, which exhibit some form of contamination. Loosely clumped together on the diagrams are surface water samples MW-1 and BH-3 (Appendix J).

#### Winds

Prevailing winds are from the north in the spring shifting to southwesterly in midsummer. Wind speeds are relatively small throughout the year, averaging 7.08 km/h (4.4 mi/h). Greatest average wind speeds recorded are in the spring at 12.87 km/h (8 mi/h) (Johnson 1983).




Figure 4. Fingerprint diagram comparing surface water sample and MW-1 sample.

### **Geological Characteristics of Coastal Plain**

In Georgia, the Coastal Plain province is characterized by a series of unconsolidated and poorly consolidated interbedded gravels, sands, and clays that lie unconformably over crystalline rocks of the Piedmont province. The Coastal Plain is bounded on the north by the Fall Line where rocks of the Piedmont province cropout and form a more resistant material than the poorly inundated Coastal Plain sediments. Composition of the Piedmont is a complex mass of Precambrian igneous and metamorphic rocks with a deeply weathered and eroded surface. Fort Benning is entirely within the Coastal Plain with the northern edge of the installation bordering the Fall Line. Proposed landfarm site lies approximately 16.09 km (10 mi) south of the Fall Line.

Coastal Plain sediments at the site are entirely Late Cretaceous age. Four formations are defined from study of outcrops in the Fort Benning area. Traditional reference in chronological order of oldest to youngest is: Tuscaloosa Formation, Eutaw Formation, Blufftown Formation, and Cusseta Sand (Appendix K). These surface units have been mapped extensively throughout the Fort Benning/Columbus area and along Chattahoochee River (Cooke 1943; Eargle, 1955; Herrick and Vorhis 1963; Marsalis and Friddell 1975; Frazier 1977; Reinhardt and Gibson 1981). However, the Eutaw Formation, Blufftown Formation, and Cusseta Sand units tend to lose their identities in the subsurface. Different authors have constructed geologic maps that place the site within different formations, for example, Eutaw Formation (Cooke 1943) and

Blufftown Formation (Eargle 1955). The most recent study of the southeastern Coastal Plain was part of the U.S. Geological Survey's Regional Aquifer-System Analysis (RASA) program, whose objectives included analysis of major groundwater systems of the United States on a regional scale. Renken et al. (1989) (Appendix B) have correlated the Coastal Plain stratigraphic units for much of the southeast from Mississippi to South Carolina.

Cretaceous sediments of the Georgian Coastal Plain consist of lithologies indicative of erosion products transported from uplifted rocks to the northwest. Following transportation, the sediments were deposited in a deltaic environment where shifting river channels, lakes, and swamps prevailed. Due to cyclical advance and retreat of the sea during the Late Cretaceous Period, depositional environments range from largely continental (fluvio-deltaic) to predominantly marine, varying laterally as well as vertically within the stratigraphic record. Along the Chattahoochee River, Blufftown, and Eutaw Formations consist of marine fossiliferous sand and calcareous silty clay, but grade into nonmarine sediments to the east toward the Ocmulgee River. Cretaceous sediments become more representative of an offshore marine depositional environment as they dip southeastward beneath younger formations.

The area of Cretaceous rocks increases in width towards the west and Cretaceous rocks thicken downdip to the southeast. In western Georgia, the surface strike of crystalline rocks on which basal Coastal Plain rocks lie is N. 77 degrees E. and their dip is approximately 14.78 m/km (78 ft per mile) in the Chattahoochee Valley with a strike of about N. 85 degrees E. Due to the fact that Blufftown and Eutaw beds become similar, Eargle (1955) was unable to trace accurately their contact, but where it was traceable, the strike was about N. 75 degrees E. Top of the Blufftown Formation strike was approximately N. 67 degrees E., dipping southeastward at a little more than 5.68 m/km (30 ft per mi).


#### Groundwater

Water table levels of the area generally are subdued replicas of land surface topography. They range from 28.04 m (92 ft) below land surface of the landfarm site to at or near surface level in low swampy areas downgradient. Precipitation not lost through run-off readily infiltrates permeable subsurface materials and moves vertically to the saturated zone and then laterally, from areas of high elevation to areas of low elevation. Lateral movement is interrupted locally by swamps, creeks, and intermittent streams into which groundwater discharges. Additional water is lost by downward leakage to lower aquifer systems and by

typical of unconfined conditions has vertical no flow boundaries beneath valleys and ridges (Figure 5). Groundwater flow at Fort Benning appears to fit this idealized model. Due to the connection of groundwater and surface water, the most easily recognizable groundwater divides for the area are boundaries of the watershed.

The subsurface is assumed homogenous and isotropic (Figure 5) where upland areas serve as recharge areas and valleys are discharge areas creating a uniform single local flow system. In reality, an infinite variety of subsurface and surface variations and anisotropic conditions exist creating regional systems of groundwater flow. However, as Freeze and Cherry (1979) noted, "... where there is pronounced local relief, only local systems develop." For purposes of the landfarm study, the watershed of Harps Creek prior to its combination with other streams was defined as the local groundwater flow system. Larger groundwater flow systems are defined as groundwater that traveled out of the watershed and discharged into larger bodies of water.

Because of the pronounced topography relief of the area, topography may be considered the major controlling aspect of groundwater flow; thus the majority of recharge of the watershed should discharge into Harps Creek. In addition, even though subsurface stratigraphy shows a great variability of sediments, ranging from permeable, well sorted medium-grained sands to clayey sands and lenses of clay, no perched water table or poorly permeable continuous unit of any significant thickness was encountered. Therefore, the study area, at a first approximation can be considered homogeneous and isotropic for studying groundwater flow.



Copying beyond Fair Use: The code on the first page of an article in this journal indicates the copyright owner's consent that copies of the article may be made beyond those permitted by Sections 107 or 108 of the U.S. Copyright Law provided that copies are made only for personal or internal use, or for the personal or internal use of specific clients, and provided that the copier pay the stated per-copy fee through the Copyright Clearance Center, Inc., 27 Congress Street, Salem, MA 01970. To request permission for other kinds of copying, such as copying for general distribution, for advertising or promotional purposes, for creating new collective works, or for resale, kindly write to the Permissions Department at the address given above. For articles in the public domain, permission to reprint should be obtained from the author.

Figure 5. Idealized cross-section of groundwater flow patterns (after Freeze and Sherry 1979, modified from Hubert, "The Theory of Groundwater Motion, *Journal of Geology*, vol 48 [1940], pp 785-944).

#### Soil

No soil types have been delineated by the SCS for the Harps Creek watershed; however, they have been defined for the Oswichee Creek watershed to the south of Harps Creek. Using similar topography as a guide, the following soils are typical of the proposed landfarm site: Cowarts, Ailey, Nankin and Troup. These soils (Table 1) range from moderately to well drained soils, with Unified Soil Classifications of sandy clay loam, sand loam, and sandy clay. They are generally less than 50 percent clay, more than 50 percent sand, and acidic. All but Nankin soils are siliceous.

#### Stratigraphy

Deep wells drilled near the site have found that combined thickness of Upper Cretaceous units is approximately 228.6 m (750 ft) with the Blufftown and Eutaw Formations comprising the upper 121.92 m (400 ft) (Meckelnburg; Marsalis and Friddell 1975). Four borings were drilled using a hollow stem auger. The location of each boring (Figure 6) was chosen to provide an understanding of local groundwater flow patterns. All were drilled to a depth of approximately 3.05 m (10 ft) below the water table and ranged in depth from 19.81 to 31.09 m (65 to 102 ft). The first boring (MW-1) is at the visual topographic high of the site and was completed as a 2-in. piezometer by installing a PVC casing and screen, and a clay seal. Aquifer characteristics were all determined at MW-1. Remaining three borings were numbered BH-2, BH-3, BH-4 with the later two located outside the landfarm site (Appendix L). Split spoon samples were taken at 5-foot intervals in all borings and geologically described (Appendix M).

Grain size analysis was performed on selected representative samples (Appendix N). Sediments were classified using the Unified Soil Classification System (USCS) (ASTM 1950) as SC, clayey sands, sand-clay mixtures; and SP, poorly graded sands, gravely sands, little or no fines. Samples from the top of BH-3 and the bottom of BH-4 were the only samples classified as CL, inorganic clays of poor to medium plasticity, gravely clays, sandy clays, silty clays, and lean clays.

Correlations and exact formation identifications from the site borings are difficult due to the lack of continuous sampling and variability of sediments within the formations. Sediments vary from bright white to tones of red and yellow with mottling of browns, purples, and greenish gray clays.




Figure 6. Topographic map of proposed landfarm region and location of borings.

Table 1. Soils typical of the site (after Frost, in print).

Soil Series	Texture	Clay %	Permeability* (in/hr)	рН	CEC (meq/100g)	Organic Matter (%)	Hydrologic Group
Ailey	Sandy Clay Loam	3-35%	0.06 – 20	4.5 to 6.5	0.3 – 2.0	0.5 – 1	В
Troup	Sandy Loam or Sandy Clay Loam	1 – 35%	0.6 – 20	4.5 to 6.5		0.5 – 1	А
Cowarts	Sandy Loam or Sandy Clay Loam	3-40%	0.06 - 6.0	4.5 to 6.5	1 – 10	0-3	С
Nankin	Sandy Loam, Sandy Clay, and Sandy Clay Loam	5-50	0.2 – 6.0	4.5 to 6.5	1.0 – 5.5	0.5 – 1	С

<sup>\*</sup>Permeability refers to ability of a soil to transmit water or air. Estimates indicate rate of downward movement of water when soil is saturated and are based on soil characteristics observed in the field, particularly structure, porosity, and texture (Johnson 1983).

Many samples were so commonly mottled and variegated that an accurate description with the Geological Society of America Rock-Color Chart (1963) was difficult. In general (Figure 7), collected sediments are: (1) sand to clayey sand with medium- to fine-grained, subangular to subrounded, quartz, (2) micaceous, and (3) containing ferruginous darker-colored clay aggregates or nodules in addition to several small lenses of noncontinuous clay units. Lignitized plant species in a clayey sand bed at the bottom of first boring were the only fossils found.

#### Sediments Beneath the Soil Horizons

Nearby hydrogeologic investigations analyzed samples from 0.91 to 14.02 m (3 to 46 ft) below the surface for CEC and moisture content (Meckelnburg 1993). CEC was found to range from 1.1meq/100g between a depth of 9.45 and 12.19 m (31 and 40 ft) to 14 meq/100 at about 9.14 m (30 ft) with and average of 5.5 meq/100 g. The cutoff between large and small CEC is 10 meq/100 g (Buol et al. 1973) indicating that most material in the unsaturated zone has a limited capacity to attenuate any potential contaminant by cation exchange. However, continuous borings may find discontinuous layers of finer materials with greater exchange capacities for contaminant retention. Moisture content for these nearby sediments typically was small, with less than 10 percent moisture content due to the well drained nature of the sediments.




Figure 7. Representative graphic log of site stratigraphy.

# 3 Site Modeling

#### **Field Data**

Groundwater levels in the monitoring well and borings ranged from 28.0 to 17.7 m (92 to 58 ft). Aquifer characteristics of MW-1 were estimated through lab analyses and slug tests. In addition, porosity and vertical hydraulic conductivity were determined in the lab from a relatively undisturbed (Shelby Tube) sample collected from bottom of MW-1. Slug tests were used to determine hydraulic conductivity and involved lowering a 3-ft by 1-in. galvanized steel slug into the well, which displaced approximately 9 in. (0.75 ft) of water. The slug was positioned below the original well water level and the time and recovery of the water levels were recorded with an In Situ "Hemit" R data recorded. Once the well water equilibrated, the slug was removed from the well, and again the time and recovery of the water levels were recorded. The computer program, AQUITEST, and the Bouwer and Rice Method (1976) were used to calculate hydraulic values (Appendix O).

Field values for hydraulic conductivity ranged from 6.60 x 10-4 to 2.91 x 10-5 cm/sec (1.30 x 10-3 to 5.72 x 10-5 ft/min). Vertical hydraulic conductivity of 1.8 x 10-4 cm/sec (3.54 x 10-4 ft/min) was determined from laboratory analysis of an undisturbed MW-1 sample. Other hydrogeologic investigations (Meckelnburg 1993; Fox 1993) within a mile radius of the site produced hydraulic conductivity values of 3.55 x 10-4 to 4.88 x 10-3 cm/sec (6.99 x 10-4 to 9.6 x 10-3 ft/min). Taking into account site variability and probable slug test error, a conductivity value of 1.4 x 10-4 ft/min was deemed reasonable. Additionally, the "undisturbed" MW-1 sample produced a laboratory porosity of 47 percent. However, in-situ soil porosity probably is much less because samples may not have been packed as tightly as when in the subsurface. Therefore, based on published porosity values for compacted sediments, a porosity of 30 percent was selected for the purpose of modeling.

#### **Groundwater Flow**

Based on the assumption of a single flow system for the study region, water table contours were determined from hydraulic heads measured in three borings, BH-2, BH-3, and BH-4. Provided that homogeneous and isotropic conditions exist, groundwater flow is perpendicular to these water table contours (Figure 8). Groundwater velocity in the saturated zone of the site along the direction of flow can be computed from the following modification of Darcy's Law (USEPA 1989):

$$v = KI / n$$
 Eq 1

where:

v = groundwater flow velocity

K = hydraulic conductivity

I = hydraulic gradient

n = effective porosity.

The resultant calculation is:

$$\left[ \left( 1.4 \times 10^{-4} \right) \left( \frac{355.5 - 350.8}{410.2} \right) \right] / \left( 0.3 \right) = 5.7 \times 10^{-6} \text{ ft / day} \left( 0.002 \text{ m / day} \right)$$




Figure 8. Direction of groundwater flow for proposed landfarm region.

#### **Numeric Groundwater Model**

The two-dimensional computer program used to stimulate groundwater flow of the site was a PC-modified version of MODFLOW, called GRAPHIC GROUNDWATER, version 1.1 (Esling and Larson 1993). Chosen because of its enhanced data input and display features, it is based on a well-documented finite difference groundwater flow modeling program.

Boundaries of the watershed were estimated from Fort Benning GIS files in combination with topographic maps. The area was discretely divided into blocks that varied from 304.8 by 304.8 m (1000 by 1000 ft) at the southern edges of the watershed to 38.1 by 38.1 m (125 X 125 ft) over the landfarm site. nonuniform grid was used to decrease computation time for each simulation; in addition, conditions farther from site will have less impact on flow at the site. The number of cells totaled 1333 (31 rows by 43 columns) (Figure 9). Vertically, cells encompassed the ground surface down to the top of the first confining layer including the water table. Elevations of the ground surface were derived from the Fort Benning Reservation Map revised in April 1962 (Corps of Engineers). The bottom depth of the unconfined aquifer was arbitrarily set at zero ft above MSL because the top of the confining layer is unknown at the site; however, nearby geological studies place it at approximately 400 ft. This is sufficient depth to have no impact on the shallow groundwater flow. Horizontal hydraulic conductivity was assumed to be greater than vertical conductivity and the model was calibrated to find the best value for horizontal conductivity.

Recharge rates were estimated from the 30-year average rainfall for Fort Benning of 123.95 cm/yr (48.8 in/yr) and the SCS method for abstractions (Chow et al. 1988). An annual rainfall of 123.95 cm (48.8 in.), normal antecedent moisture climate, and a soil hydrologic group of B was used to calculate run-off. Run-off was computed at 113.79 cm/yr (44.80 in/yr) with an infiltration rate of 10.16 cm/yr (4.0 in/yr) (Appendix P) equaling a net recharge for the study region of 1.83 x 10-7 m/min.(6 x 10-7 ft/min). In addition, the watershed was divided into four recharge zones that received 100, 75, 25, and zero percent of available recharge depending on topography of the grid cell. Grid cells with an elevation greater than 400 ft received 100 percent of total available recharge, whereas cells with an elevation less than 300 ft received no recharge and were considered areas of discharge. Insufficient data for Harps Creek and its tributaries required that parameters of riverbed conductivity, riverbed thickness, river stage heights, and river widths be estimated solely by calibration of the model.




Figure 9. Discrete division of Harps Creek watershed for groundwater modeling.

Table 2	Hydraulic	head '	عمينادي	for the	eteady	state mode	ı.
i abie 2.	nvuiaulic	neau	values	ioi ille	Steauv	State mode	<i>:</i> I.

Node (i,j)	Well or Bore Hole	Measured Hydraulic Head (ft)	Simulated Hydraulic Head (ft)	Difference (hm - hs)
25,10	MW-1	356.93	353.71	3.22
32,10	BH-2	360.83	358.76	2.07
24,16	BH-3	348.79	350.00	-1.21
17,5	BH-4	347.56	347.70	-0.14

Mean Error (ME) = 0.985 ft

Mean Absolute Error (MAE) = 1.66 ft

Root Mean Squared (RMS) Error = 2.01 ft

The calibrated model reached steady state conditions and reproduced all known hydraulic heads within acceptable values (Table 2). A contour map of computed watertable elevations in the watertable aquifer under steady state conditions (Figures 10 and 11) indicates a south-southwesterly direction of groundwater flow that is influenced strongly by topography and surface water drainage patterns. Due to uncertainties in calibration and parameter values used, the model may not represent the system accurately under a different set of boundary conditions or hydraulic stresses. Additional borings are needed to provide greater details of groundwater flow patterns at the site.

Simulations of different transient conditions were applied to the computer model to determine the effect of extreme rain events on the hydrologic flow regime of the site. Based on information from the U.S. Weather Bureau data, a 100-year return period storm with a 24-hour duration is 22.53 cm (8.87 in) of rainfall (Hershfield 1961) (Appendix Q). Rainfall was divided into six periods according to the SCE rainfall distribution for a 24-hour storm (Chow et al. 1988) with each period covering 4 hours. These amounts were entered uniformly as recharge rates to the site. Simulations were run using a recharge rate of 12 percent of available rainfall and a worse-case condition of 100 percent recharge of total rainfall infiltrated to the groundwater (Appendix R). In addition, specific yields of the aquifer were varied from 0.3, the maximum for a medium sand, to 0.07, an average for a sandy clay (Fetter 1988).

Results of these simulations showed that little change occurs in groundwater flow patterns from steady state to transient conditions. The difference between a recharge of 12 percent compared with a maximum recharge of 100 percent is one of magnitude rather than any significant change (Appendix S). The water table rose dramatically, as expected, from such a severe 24-hr/100-yr storm. Thus, groundwater flow rates increased dramatically. Other computer software programs specifically geared toward modeling the unsaturated zone must be used for a more complete picture of groundwater movement at the site.




Figure 10. Potentiometric surface of the water table aquifer.

34 USACERL TR-97/136




Figure 11. Direction of groundwater flow in the water table aquifer.

USACERL TR-97/136 35

#### **Summary and Conclusions**

Proposed Fort Benning landfarm site consists of typical Coastal Plain sediments that are permeable and acidic with some clay and a mean grain size distribution of medium to fine sand. Site soils are a sandy clay loam with small values for CEC, organic content, and moisture content. No perched watertable was discovered during subsurface exploration to suggest the existence of a natural clay barrier or a confining unit with reduced permeability. The watertable is a subdued replica of topography with an unsaturated zone that probably is greater than 15.24 m (50 ft), even following extreme rainfall events. A small hydraulic gradient exists across the site that increases down gradient towards the Groundwater flow is to the south-southwest. Evapo-transpiration rates as great as 70 percent of total yearly precipitation limits the amount of infiltrating water. Rainwater that does infiltrate travels primarily vertically to the watertable and then horizontally to downgradient creeks. Water bodies potentially affected by placement of a landfarm within this hydrogeologic system are Harps Creek and downgradient Oswichee Creek. Drinking water for the region is supplied primarily by a surface water source and a few rarely used wells that tap deep aquifers protected by a confining unit. Both types of water sources are upgradient with no known drinking water sources within 24.1 km Limitations of the Fort Benning (15 miles) downgradient from the site. subsurface can be overcome by construction of a clay and/or synthetic layer and use of soil enhancement techniques such as addition of lime and mineral nutrients to the soil.

Because shallow groundwater of the region flows directly into local creeks, the greatest concern is possible mobilization of landfarm contaminants by infiltrating rainwater that might reach the water table still in significant concentrations. These concerns are minimized by numerous studies conducted on the fate of hydrocarbons in the subsurface. Studies concluded that even poor quality soils similar to those at Fort Benning have the ability to greatly reduce petroleum concentration through retardation and biodegradation. Expectations of little to no migration of contaminants are further confirmed by documented experiences of the Fort Polk landfarm (Smith et al. 1992).

Landfarm technology has been researched thoroughly for a variety of environments and found to be a safe alternative even in imperfect sites. The contaminant potential of landfarm organics in the subsurface is based on the specific hydrogeology of the site, type of wastes incorporated, and management strategies of the landfarm. Reliable monitoring of the physical properties of the landfarm matrix, in addition to monitoring local creeks and groundwater, will

allow for rapid pollution detection at the Fort Benning landfarm and, consequently, adoption of management modifications to interrupt any possible migration process.

### 4 Subsurface Modeling

#### **Field Data**

Seven soil borings have been drilled at the site with soil samples taken every 1.5 m (5 ft). A split spoon sampler was used to classify the soils and to determine the groundwater elevation of each boring. Because of cost considerations, three borings were filled in after water elevation was determine; other four soil borings have been converted into monitoring wells. Sandy material with some thin clay layers predominated in the soil borings (Appendix L).

The four monitoring wells were logged using an induction conductivity log and a gamma log (Appendix T) to determine location of clay layers. Graphing of clay layers at their respective heights shows with some certainty that there is one continuous clay layer underneath the entire site (Appendix U). Undisturbed samples taken at the bottom of the four monitoring wells were test for in-situ density (pcf), moisture content, hydraulic conductivity, and soil characteristics (Table 3).

#### Modeling

The 2-dimensional computer modeling program used to simulate the flow of water and contaminates through saturated and unsaturated layers, FEMWATER and LEWASTE (Yeh and Chang, 1993a, b), were developed under the direction of the U.S. Army Corps of Engineers with support from the U.S. Department of Defense, the U.S. Department of Energy, and the U.S.

Table 3. Sample test results.

Boring No.	Sample Date	Depth (ft)	In-Situ Density (pcf)	Moisture Content (%)	Hydraulic Conductivity K (cm/s)	Soil Description
MW-1	13 Jun 94	102			1.8 x 10-4	Sand, trace clay, organic matter
MW-2	24 Oct 95	94-96	127.9	23.83	1.4 x 10-4	Silty sand, trace of clay, yellow
MW-3	23 Oct 95	74-76	107.54	7.3	8.5 x 10-4	Sand, some silt, trace of clay, yellow
MW-4	25 Oct 95	84-86	126.4	22.5	1.02 x 10-4	Silty sand, trace of clay, trans yellow

Environmental Protection Agency. Visualization of FEMWATER and LEWASTE were interfaced with a graphics software (Groundwater Modeling System (GMS)) package developed by the Engineering Computer Graphics Laboratory (ECGL) of Brigham Young University for the Department of Defense (GMS 1995). For purposes of viewing in GMS, the model was converted to a 3-dimensional model. This was accomplished by

Table 4. Time increments.

Time in sec	Time
300	5 min
660	11 min
2203200	25.5 days
165210000	5.24 yr
375830016	11.9 yr
586460032	18.6 yr
797080000	25.3 yr
886600000	28.1 yr

putting one 2-dimensional model 30.5 cm (1 ft) in back of the other. Using the GMS film loop, the simulation can be viewed showing the contamination plume in time increments of Table 4.

A 2-dimensional grid was used for imputing into FEMWATER and LEWASTE. Grid was made up of a total of 2420 elements and 2520 nodes with 55 elements in the x-direction and 45 elements in the z-direction. Bottom nodes were set at an elevation of zero. Top nodes were set according to the surface elevation of the site with a maximum elevation of 4175.76 cm (137 ft). Grid was lined up in the direction of groundwater flow. At the bottom of the grid, spacing in z-direction was 365.76 cm (12 ft) while spacing at the top is (15.24 cm (0.5 ft). This was done to keep number of nodes to a minimum and create more definition of the 2-dimensional grid near the ground surface (Appendix V). Grid spacing in the x-direction is 2011.68 cm (66 ft), except near the site, where spacing is decreased to simulate a 152.4 cm (5 ft) clay wall for the site. For purposes of viewing in GMS, 2-dimensional grid was converted to a 3-dimensional grid by putting one 2-dimensional grid 30.48 cm (1 ft) in back of the other. The 3-dimensional grid is made up of 2420 elements and 5040 nodes. Front face of the elements is the same size as the 2-dimensional model.

A program without a clay liner placed under the treatment area, without natural occurring clay layers, and with all sand was set up to simulate a worst case scenario. Amount of rain normally infiltrating into the groundwater is 12 percent of annual rainfall (Kundell). An average rainfall of 124 cm/yr (48.8 in./yr) would create an infiltration rate of 14.87 cm/yr (5.856 in./yr). To create a worst case scenario, infiltration rate of rainwater was doubled to 29.748 cm/yr (11.712 in./yr). Test results from three undisturbed samples taken from monitoring wells (MW) 1, 2, and 4 had an average hydraulic conductivity (K) of 1.4 x 10-4 cm/s (2.76 x 10-4 ft/min). To further create a worst case scenario, hydraulic conductivity was increased to 5.8 x 10-3 cm/s (1.4 x 10-2 ft/min). Finally, two distribution coefficients (Kd) were used; the first Kd was set at 100 ml/g which would be a realistic value for soil at Fort Benning. The second Kd was set at 10

USACERL TR-97/136 39

ml/g, for a worst case scenario. Smaller distribution coefficient allows contaminate plume to travel faster. Assumptions also included those made for FEMWATER and LEWASTE (Appendix W).

A second simulation added a clay layer with a hydraulic conductivity of  $9.0 \times 10^{-5}$  cm/s (1.77 x 10-4 ft/min) located 1828.8 cm (60 ft) below the surface of the site with an average thickness of 335.28 cm (11 ft) as suggested by the logs from the monitoring wells. This simulation also included an added clay liner 152.4 cm (5 ft.) thick creating a "pit" 106.68 cm (3.5 ft) deep and 11917.68 cm (391 ft) across with a hydraulic conductivity of  $9.00 \times 10^{-8}$  (2.95 x 10-9 ft/s) where contaminated soil would be treated by "farming." Assumptions were made for FEMWATER and LEWASTE (Appendix W) and for the clay (Appendix X).

#### 5 Conclusion

Simulations are not calibrated models; they are worst case scenarios. Simulation of treatment area without a layer can be compared to the simulation with a layer as to total distance contamination traveled in the z-direction. Soil was considered contaminated if this value was above 0.002, which is 0.2 percent of starting contamination. Using this comparison, contamination in simulation without the clay liner traveled 731.52 cm (24 ft), whereas contamination in the simulation with the liner traveled 396.24 cm (13 ft). Contamination in the simulation without a constructed barrier moved nearly twice the distance contamination moved with a clay layer over the 28.1 year period. However, this method of comparison may not be the most accurate interpretation because the soil becomes saturated in the simulation with the clay liner. Contamination moves very quickly through saturated soil and once it gets through the saturated zone it begins moving slower. Simulation without the clay liner depicts slow but steady movement that outpaces contamination in the simulation with a clay liner.

Another way to compare the simulations is to look at distance traveled by contamination beyond the depth of the clay liner. In the simulation with a clay liner, the contamination moved 144.78 cm (4.75 ft) beyond the liner. Simulation without a clay liner showed a movement of 480.06 cm. (15.75 ft) beyond the depth where the clay liner would have been located. Contamination in the simulation without the clay liner moved more than three times as far as in the simulation with the liner over the time period of 28.1 years.

Simulations are worst case scenarios for several reasons:

- 1. Hydraulic conductivity has been set higher than actual site conditions allowing water to travel through soil faster.
- 2. Program limitations assign the liner a hydraulic conductivity of 9.00 x 10-8 cm (2.95 x 10-9 ft/s), but geosynthetic clay liner may have a lower hydraulic conductivity.
- 3. Soil within the clay liner is fully saturated in the simulation, which will not be allowed under operating conditions. Soil being saturated creates a higher

concentration of contamination and increases speed at which the contamination plume moves within the clay liner.

- 4. Models do not have any decay factors that would simulate bioremediation that would take place.
- 5. Infiltration rate was doubled compared to expected amount.
- 6. Although the natural occurring clay layer, believed to be located 1828.8 cm (60 ft) below proposed landfarm surface, does not make a substantial difference in the simulation, it provides an added amount of security. A natural occurring clay layer would create an added barrier with the ability to trap contaminants because of the clay's cation exchange capacity (CEC).

This study concludes that the site Fort Benning, GA is suitable for a landfarm because of distance to groundwater, slow speed at which contaminants would travel in the unsaturated zone, and the added security that clay provides through cation exchange capacity.

#### References

- Aller, L., T. Bennett, J.H. Lehr, R.J. Petty, and G. Hackett, DRASTIC: A Standardized System for Evaluating Ground Water Pollution Potential Using Hydrogeologic Settings, EPA-600/2-87-035 (U.S. Environmental Protection Agency [USEPA], 1987), 455 pp.
- ASTM Committee D-18 on Soils for Engineering Purposes, Procedures for Testing Soils: Nomenclature and Definitions, Standard Methods, Suggested Methods (American Society for Testing and Materials [ASTM], Philadelphia, PA, 1950), 418 pp.
- Bouwer, H., and R.C. Rice, A Slug Test for Determining Hydraulic Conductivity of Unconfined Aquifers With Completely or Partially Penetrating Wells: Water Resources Research, vol 12, No. 3 (1976), pp 423-428.
- Brassington, R., Field Hydrogeology (Halsted Press, New York, 1988), 175 pp.
- Buol, S.W., F.D. Hole, and R.J. McCracken, Soil Genesis and Classification (The Iowa University Press, Ames, 1973), 360 pp.
- Chow, V.T., D.R. Maidment, and L.W. Mays, *Applied Hydrology* (McGraw-Hill, Inc., New York, 1988), 572 pp.
- Cooke, C.W., Geology of the Coastal Plain of Georgia, U.S. Geological Survey Bulletin, vol 941 (1943), 121 pp.
- U.S. Army Corps of Engineers, Fort Benning Reservation Map A: Fort Benning Georgia, Scale 1:25,000, 1 sheet (1962).
- Davis, K.R., J.C. Donahue, R.H. Hutcheson, and D.L. Waldrop, Most Significant Ground-Water Recharge Areas of Georgia: Georgia Geologic Survey, Hydrologic Atlas 18, Scale 1:500,000,1 sheet (1992).
- Eargle, D.H., Stratigraphy of the Outcropping Cretaceous Rocks of Georgia U.S. Geological Survey Bulletin, vol 1014 (1955), 100 pp.
- Esling, S.P., and T.A. Larson, *Graphic Groundwater*, Version 1.1 (Micro-Innovations, Inc., 1993), 79 pp.
- Fox, W.A., Closed Jamestown Road Landfill Fort Benning, Georgia [unpublished] (U.S. Army Environmental Hygiene Agency, Geohydrologic Study No.38-26-KW28-93, 12-22 (July 1993), 10 pp.
- Frazier, W.J., A Guide to Tuscaloosa, Eutaw, and Blufftown Formations in Muscogee and Chattahoochee Counties, Georgia (Earth Science Department Columbus College, 1977), 9 pp.

- Freeze, R.A., and J.A. Sherry, *Groundwater* (Prentice-Hall, Inc., Englewood Cliffs, NJ, 1979), 604 pp.
- Frost, L., Classification and Correlation of the Soils of Chattahoochee and Marion Counties, Georgia (U.S. Department of Agriculture, Soil Conservation Service, in print).
- Geological Society of America, Rock-Color Chart (GSA, New York, NY, 1963).
- Georgia Department of Natural Resources, Rules of Georgia Department of Natural Resources, Environmental Protection Division, Criteria for Protection of Groundwater Recharge Areas (State of Georgia, Chapter 391-3-16-.02, Revised December 20, 1991), pp 6-9.
- Hem, J.D., ed., Study and Interpretation of the Chemical Characteristics of Natural Water, 3d ed., Water Supply Paper 2254 (U.S. Geological Survey, 1985), 263 pp.
- Herrick, S.M. and R.C. Vorhis, Subsurface Geology of the Georgia Coastal Plain, Information Circular 25 (Georgia Geological Survey, 1963), 73 pp.
- Hershfield, D.M., Rainfall Frequency Atlas of the United States for Durations From 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years, Technical Paper No. 40 (National Weather Bureau, Washington, DC, 1961), 115 pp.
- Hubert, M.K., "The Theory of Groundwater Motion," Journal of Geology, vol 48 (1940), pp 785-944.
- Johnson, J.H., Soil Survey of Muscogee County, Georgia (U.S. Department of Agriculture, Soil Conservation Service, 1983), pp 1-82.
- Kundell, J.E., Ground Water Resources of Georgia (Institute of Government, University of Georgia, 1978), 68 pp.
- Marsalis, W.E., and M.S. Friddell, A Guide to Selected Upper Cretaceous and Lower Tertiary Outcrops in the Lower Chattahoochee River Valley of Georgia, Georgia Geological Survey Guidebook 15 (1975), 79 pp.
- Meckelnburg, T.S., Active Landfill Fort Benning, Georgia, (unpublished) Geohydrologic Studies No. 38-26-K18X-93 (U.S. Army Environmental Hygiene Agency, 7-23 June 1993) and No. 8-12 U.S. Army Environmental Hygiene Agency, July 1993), 30 pp.
- Miller, J.A.. and R.A. Renken, Nomenclature of Regional Hydrogeologic Units of the Southeastern Coastal Plain Aquifer System, Water-Resources Investigations Report 87-4202 (1988), 21 pp.
- Reinhardt, J. and T.G. Gibson, Upper Cretaceous and Lower Tertiary Geology of the Chattahoochee River Valley, Western Georgia and Eastern Alabama (Georgia Geological Society, 16th Annual Field Trip, 1981), 80 pp.
- Renken, R.A., G.L. Mahon, and M.E. Davis, Hydrogeology of Clastic Tertiary and Cretaceous Regional Aquifers and Confining Units in the Southeastern Coastal Plain Aquifer System of the United States, U.S. Geological Survey Hydrologic Investigations, Atlas HA-701 (1989), 3 sheets.

- Smith, J. L., J.D. Grafton, and D.K. Mann, Landfarm Technology at Fort Polk, Louisiana: Lessons Learned, Special Report N-92/11/ADA247930 (U.S. Army Construction Engineering Research Laboratories [USACERL], March 1992), 18 pp.
- The Terrain Analysis Center, Fort Benning Georgia, Terrain Analysis (U.S. Army Engineer Topographic Laboratories, Fort Belvoir, VA,1976), p 57.
- Trent, V.P., Ground-Water Pollution Susceptibility Map of Georgia, Georgia Geologic Survey, Hydrologic Atlas 20, scale 1:500,000 (1992), 1 sheet.
- Twait, S., Subsurface Modeling of Fort Benning Landfarm Site, thesis in preparation (University of Illinois, Urbana-Champaign, 1997).
- U.S. Army Toxic and Hazardous Materials Agency (USATHAMA), Preliminary Site Inspection for Fort Benning Military Reservation, (unpublished) Site Inspection Report No. 91032 (U.S. Army Corps of Engineers, 1992), 82 pp.
- U.S. Environmental Protection Agency, EPA Ground Water Handbook (Government Institutes, Inc., Rockville, MD, 1989), 212 pp.
- Weiss, M.M., A Hydrogeologic Assessment of a Proposed Landfarm Site at Fort Benning, Georgia, unpublished thesis (University of Illinois at Urbana-Champaign, 1995), 95 pp.
- Yeh, G.T. and J.R. Chang, User's Manual: A Finite Element Model of WATER Flow Through Saturated-Unsaturated Porous Media, Version 2.0 (Pennsylvania State University, University Park, PA, 1993a).
- Yeh, G.T. and J.R. Chang, User's Manual of a Hybrid Language-Eularian Finite Model of WASTE Transport Through Saturated-Unsaturated Media, Version 2.0 (Pennsylvania State University, University Park, PA, 1993b).

### **Appendix A: Loading Calculations**

Estimated oily waste produced annually at Fort Benning: 100,000 lbs

Allowable oily waste loading per application: 1%

Estimated treatment or actual "farming" area: 5 acres

Estimated treatment area in square feet: 217,800 ft<sup>2</sup>

1 acre =  $43,560 \text{ ft}^2$ 

 $43,560 \text{ ft}^2 \text{ x } 5 = 217,800 \text{ ft}^2$ 

Capacity of 6 inches (0.5 ft) of soil over 5 acres: 108,900 ft<sup>3</sup>

 $217,800 \text{ ft}^2 \times 0.5 \text{ ft} = 108,900 \text{ ft}^3$ 

Estimated soil weight for 108,900 ft<sup>3</sup>: 11,979,000 lbs

 $1 \text{ ft}^3 \text{ of soil} = 110 \text{ lbs}$ 

 $108,900 \text{ ft}^3 \text{ x } 110 \text{ lbs} = 11,979,000 \text{ lbs}$ 

Total capacity to assimilate oily waste at 1% application: 119,790 lbs

 $11,979,000 \text{ lbs } \times 0.01 = 119,790 \text{ lbs}$ 

Estimated sludge loading annually at Fort Benning  $500 \text{ yd}^3$   $500 \text{ yd}^3 \times 27 = 13,500 \text{ ft}^3$   $13,500 \text{ ft}^3$ 

Sludge weight per ft<sup>3</sup> 100 lbs 13.500 ft<sup>3</sup> x 100 1,350,000 lbs

Dry solid percentage **0.5** % 1,350,000 x .5 = 675,000 lbs **675,000** lbs


Estimated treatment or actual "farming area" 5 acres 675,000 lbs /5 = 135,000 lbs dry solids per acre 1135,000 lbs

Assuming 2.25% nitrogen content in dried sludge 2.25% 135,000 lbs x .0225 = 3,037.5 lbs nitrogen per acre 3,037.5 lbs

# Appendix B: Southeastern Coastal Plain Stratigraphic Correlation Chart

		MISSISSIPPI	ALABAM	1A	GE(	ORGIA	SOUTH CAF	ROLINA
	North	Central-East	West	East	West	East	Southwest	Northeast
			d terrace deposits			Alluvium and ter	race deposits	
		Citrone	elle Formation	<b>*</b>				
		Catahoula Sandatone				rn Formation		1
<b>A1</b>	Glendon, A	larianna and Mint Springs For Forest Hill Formation	nations	Suwar	nee Limestone			l
C1		Yazoo Formation	77777	Ocala Limest	one —		Barnwell	-
		ook Mountain Formati	on Gosport Sa	ind:	von Park Form	ation San	ee Formation	İ
A3		Sparta Sand	Lisbon Formation	on 🗔		Olderner I		
			Formation		atta Formation	Formation	Black Mingo	_
	1.	an Sand Member	Nanafalia Formation	Tuscahoma Clayton Fo	Formation.	Cadar Keys Formation	Formation For	mation
cz		Porters Creek Formatic	on	Pro	vidence Sand	Lawson	Black Creek Form	tion
АЗ	Ripley Formation				ey Formation Cussetta San	d		
	Formati	, S	Selma.		Blufftown F		Middendorf Forme	A
C3			Group		z,		Mildeliacti	
	Coffee S	ind 2			Eulaw Fo	rmation (upper p	art)	
A4		2	Shan Formations	Euton E	ormation		Ça <sub>l</sub>	e Fear
		Tuscaloosa G			E	Basal part of :: Itaw Formation	FOI	A
	i i	locks of Early Cretaceo		Tusc For	aloosa nation Atki	nson Formation	Unnamed	
	2002	50/30/30/1-15/5/5/	75/27/75/27/27/25/25	571-1828	\$227.5027.55	(E);7:5(\$2\;7:2)	\$\$\$\$=\$#\$ <b>¥</b> \$&\$	777725
		<b>然此系统的</b>	ndifferentlated rocks	of Jurassic, <u>いいいい</u>	Triassic, and (o	r) Paleozoic age	3.83663336	经总验
			EX.	PLANA				
			<b>6</b> /4/22	Surficial	aquifer			
				Upper co	nfining unit			
				Floridan a	aquifer system			
		SOU'	THEASTERN CO	Dastal P	LAIN AOLIIF	ER SYSTEM	!	
	88	A1, aquifer unit	(2)21	C2, confinir			A4, aquifer unit	
	P	C1, confining un	it Fixed	A3, aguifer	-	1557	Base of System	
		A2, aquifer unit		C3, confinin			Absent	

(Source: Miller and Renken, 1988)



### Appendix C: Fort Benning Temperature, Wind Speed, and Humidity Data

Fort Benning Temperature, Wind Speed, and Humidity Data

	Tempera	iture (F)	Wind Sp	eed (mi/hr)	Relative Humidity
Month	Mean Daily Max	Mean Daily Min	Mean	Max	Mean Percent
January	59.0	36.0	5.8	48.3	59
February	61.0	39.0	5.8	55.2	56
March	68.0	44.1	6.9	70.2	52
April	78.1	52.2	5.8	55.2	49
May-	84.0	60.1	4.6	80.6	49
June	90.0	68.0	3.5	73.3	53
July	91.0	71.1	3.5	80.6	59
August	91.0	70.0	3.5	63.3	56
September	86.0	65.0	3.5	59.9	55
October	79.0	53.1	3.5	47.2	50
November	66.9	42.1	4.6	50.6	52
December	60.1	37.9	4.6	54.1	58
Annual	75.9	53.1	4.6	80.6	54
No. of Years on Record	32	32	34	32	33

Source: USTHAMA 1992 taken from USAF Air Weather Service Climatic Brief for Fort Benning, Georgia (Lawson AAF), period of record May 1939 to December 1972, with extremes updated through December 1981.

## **Appendix D: Yearly Precipitation Totals** for Fort Benning Georgia

Yearly Precipitation Totals for Fort Benning, Georgia

Year	Amount (inches)	Year	Amount (inches)	Year	Amount (inches)
		1071	56.24	1982	51.89
1960	45.76	1971	56.24		
1961	43.70	1972	51.90	1983	55.69
1962	36.04	1973	57.20	1984	38.20
1963	41.46	1974	45.99	1985	43.10
1964	64.37	1975	62.63	1986	39.21
1965	40.29	1976	52.02	1987	37.50
1966	58.76	1977	46.60	1989*	60.74
1967	46.28	1978	58.25	1990	39.93
1968	38.27	1979	67.50	1991	56.45
1969	39.25	1980	50.55	1992	47.27
1970	46.82	1981	47.31	1993	47.96

<sup>\*</sup> Year 1988 had incomplete precipitation totals.

Smallest and largest yearly precipitation totals are in bold.

(Source: National Climate Center, Ashville, North Carolina)

### **Appendix E: Fort Benning Precipitation**


**Fort Benning Precipitation** 

Month	Mean (in.)	Greatest (in.)	Least (in.)	Max 24-Hour (in.)
January	4.0	9.1	0.9	4.7
February	4.1	8.2	0.9	4.1
March	5.3	16.8	0.8	4.4
April	4.4	12.3	0.4	5.5
May	3.3	9.9	0.1	3.1
June	4.0	9.4	0.8	3.4
July	5.7	15.8	1.0	3.2
August	4.1	12.3	0.5	0.6
September	3.3	8.9	*	3.1
October	1.6	7.3	*	4.4
November	2.7	13.2	0.1	4.4
December	4.9	11.1	0.6	4.0
				•
Annual	47.4	76.3	24.8	5.5

<sup>\*</sup> Less than 0.04 inches

Source: USTHAMA 1992 taken from USAF Air Weather Service Climatic Brief for Fort Benning, Georgia (Lawson AAF), period of record May 1939 to December 1972, with extremes updated through December 1981

## Appendix F: Average Monthly Precipitation for Fort Benning, GA



(Source: National Climate Center, Ashville, North Carolina AWS Climatic Brief for Fort Benning, Georgia (Lawson AAF), period of record 1969 to 1993.)

52 USACERL TR-97/136

### Appendix G: Description of Water Quality Analysis

Two water samples were collected from each of the four boreholes and from a downgradient surface water source (Figure xx). Prior to collection of water samples, stagnant water was removed from the bore holes with a bailer (a well volume) and samples were taken from water that had refilled the well to its original level. One well volume was removed from boreholes and water samples were collected while the auger stem was still in place. MW-1 was purged with three well volumes removed prior to sampling. Redox potential, temperature, pH, and specific conductance of water samples were measure onsite. All sets of samples were maintained at a temperature below 4° C (39.2° F) with one set acidized for total iron concentration measurements. Samples then were transported to the U.S. Army CERL chemical laboratory where each was filtered and pH, specific conductance, and total iron were measured in addition to major anion and cation concentrations: HCO<sub>3</sub>-, Cl-, NO<sub>3</sub>-, SO<sub>4</sub>-, NA+, NH<sub>4</sub>, K+, Mg++, and Ca++.

Measurement of major anion and cation concentrations were made using chromatography analysis on a Waters LC-Module 1 solvent delivery system equipped with a Waters 431 conductivity detector. Data were collected and manipulated using a Dell 386 computer with Maxima 820 software. Standard solutions for all analyte ions were prepared by dilution from appropriate stock solutions and were used to generate calibrations curves. Sample analyte concentrations were determined by manipulation of Maxima software. Total iron concentrations were measured by atomic absorption analysis on a Perkin Elmer 303B Atomic Absorption Spectrophotometer. A blank as well as a fresh standard were run to create a calibration curve and samples were aspired and analyzed for iron.

Sample may have been affected by limited sampling methods, inadequate purging, or prior activity at the site. Limestone roadfill at the site may be the cause of increased levels of calcium, carbonate, and sulfate concentrations found in BH-2 sample. The acidic sample from BH-4 had an increased level of nitrate, which may indicated septic tank or other nutrition-causing contamination sources. Also, levels of iron in water sample may have been increased artificially when the samples were acidized prior to filtration. Small shifts in pH or Eh can cause great changes in iron solubility; thus, increasing quantities of iron go into solution as pH values drop below 4.8 (Hem 1985). Despite these sampling questions, trends are observable. Surface water and groundwater samples from MW-1 are similar. Their small dissolved solids content and similar fingerprints imply that they come from the same source, rainwater.

### **Appendix H: Water Quality Analysis**

Sample ID Sampling Date	MW-1 6/17/94	BH-2 6/15/94	BH-3 6/15/94	BH-4 6/16/94	Surface 6/16/94
FIELD MEASUREMENTS					
temperature (°C)	21.6	26.9	23.5	22.6	22.8
specific conductance (µmhos/cm)	50	120	50	170	20
redox potential (mV)	208		295	201	110
LAB MEASUREMENTS					
pH (in lab on 6/21/94)	5.53	6.99	5.70	3.56	5.00
carbonate (mg/L)	5.04	47.7	16.5	3.4	4.93
chloride (mg/L)	10.1	5	4.79	22.4	4.87
nitrate (mg/L)	12.6	4.17	9.7	36.3	4.22
sulfate (mg/L)	5.22	24.9	8.46	12.5	4.88
sodium (mg/L)	2.76	4.78	2.52	7.74	1.72
ammonia (mg/L)	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01
potassium (mg/L)	0.67	1.28	0.88	0.78	0.62
magnesium (mg/L)	0.55	0.95	0.85	0.71	0.35
calcium (mg/L)	3.36	16.8	4.2	5.92	1.09
total iron (mg/L)	0.11	8.14	16.9	23.63	8.39

Conducted by the chemical laboratory of the U.S. Army Construction Engineering Research Laboratories, Champaign, Illinois.

## Appendix I: Background Water Quality From a Landfill North of Site


Sample ID Lab # Sampling Date	K C4502 7/10/93	P C4541 7/9/93							
GENERAL PARMETERS									
temperature (°C)	20.9	19.5							
pH	3.5	3.9							
specific conductance (µmhos/cm)	35	51							
dissolved oxygen (ppm)	6.9								
DISSOLVED METALS (mg/L)		<del></del>							
silver	< 0.010	< 0.010							
arsenic -	< 0.0010	< 0.0010							
barium	< 0.010	0.013							
beryllium	0.001	0.001							
cadmium	< 0.0005	< 0.0005							
cobalt	< 0.050	< 0.050							
chromium	< 0.020	< 0.020							
copper	< 0.025	< 0.025							
mercury	0.000226	0.000347							
nickel	0.000168	0.000433							
lead	< 0.0010	0.0012							
antimony	< 0.0005	< 0.0005							
selenium	< 0.01	< 0.01							
thallium	0.00146	< 0.0005							
vanadium	< 0.050	< 0.050							
zinc .	< 0.015	0.399							
TOTAL METALS (mg/L)									
silver	< 0.010	< 0.010							
arsenic	< 0.0010	< 0.0010							
barium	0.038	0.026							
beryllium	0.001	0.001							
cadmium	0.000897	0.00223							
cobalt	0.072	< 0.050							
chromium	< 0.020								
copper	< 0.025	•••							
mercury	0.000459	< 0.0001							
nickel	0.000253	0.000488							
lead	0.0077	0.0202							

Sample ID Lab # Sampling Date	K C4502 7/10/93	P C4541 7/9/93	
TOTAL METALS continued (mg/L)			
antimony .	< 0.0005	< 0.0005	
selenium	< 0.01	< 0.01	
thallium	<0.0005	< 0.0005	
vanadium	< 0.050	< 0.050	
zinc	0.067	•••	
NON-METALS INORGANICS			
ammonia (mg/L)	0.44	0.69	
chloride (mg/L)	2.1	1.4	
total cyanide (mg/L)	< 0.01	< 0.01	
nitrite + nitrate as N (mg/L)	0.11	1.2	
total organic carbon (mg/L)	0.99	1.3	
total organic halogens (TOX) (µg/L)	20	29	
sulfate (mg/L)	< 1.0	2.1	
ORGANIC COMPOUNDS (µg/L)			
acetone	7*	< 4.4*	
2-butanone	< 2	< 2	
dichlorodifluoromethane	5	< 2	
1,1-dichloroethane	< 2	< 2	
1,1-dichloroethene	< 2	< 2	
methylene chloride	< 2	< 2	
tetrachloroethene	< 2	< 2	
1,1,1-trichloroethane	< 2	< 2	
trichlorofluoromethane	31	< 2	
bis(2-ethylhexyl)phthalate	5**	7**	
phenol	< 10	< 10	


- Indicates that analyte was found in the associated blank as well as in the sample.
- \*\* indicates that the reported value is an estimate and that the analyte was found in the associated blank as well as in the sample.

(Source: Meckelnburg 1993)

### Appendix J: Water Analysis Scatter Diagram



## Appendix K: Generalized Section, Muscogee to Randolph Counties



### Appendix L: 1994/1995 Drilling Logs

ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CHROLE SUITE A TUCKER, CEORCIA 30084 404 - 308-0809 FAX 908-8802

LOG OF BORING

SHEET 1 OF 2

DESCRIPTION		NAME: LAND FARY PROJECT, FT. BE BAILEY WARD, PIEDMONT ENVIRONMENT				A BOL Die			LOGGED BY:	06/13/94 pnp
BROKEN ASPHALT  SAND-FINE TO MEDIUM, DRY; DENSE; PRED-ORANGE (COASTAL SEDIMENT)  5  2  11  7-22-23 16*  SEIVE TEST  BENTONITE SEAL  5  CLAY-STIFF, MCIST, GREY AND SAND-FINE; TAN INTERSEDDED IN 1°TO 5° LAYERS  20  5  8-16-20 16*  HYDROMETER TEST  W=14,37/ S.G.=2.9  10  11  7  24-32-36 18*  SEIVE TEST  83  30  7  24-32-36 18*  SEIVE TEST  9  10  11  11  12  13  14  15  16  16  17  18  18  18  SEIVE TEST  18  19  10  10  11  11  11  12  13  14  15  16  16  16  17  18  18  18  SEIVE TEST	DAILET XAID, TIESMONT CHVINGANCTI									
BROKEN ASPHALT  SAND-FINE TO MEDIUM, DRY; DENSE; PRED-ORANGE (COASTAL SEDIMENT)  5  2  11  7-22-23 16*  SEIVE TEST  BENTONITE SEAL  5  CLAY-STIFF, MCIST, GREY AND SAND-FINE; TAN INTERSEDDED IN 1°TO 5° LAYERS  20  5  8-16-20 16*  HYDROMETER TEST  W=14,37/ S.G.=2.9  10  11  7  24-32-36 18*  SEIVE TEST  83  30  7  24-32-36 18*  SEIVE TEST  9  10  11  11  12  13  14  15  16  16  17  18  18  18  SEIVE TEST  18  19  10  10  11  11  11  12  13  14  15  16  16  16  17  18  18  18  SEIVE TEST   ELEV.	DESCRIPTION	T T T T	NO.	TYPE	RIME	5 /6° b	ETTN	NOT	ES	
1		SAND-FINE TO MEDIUM, DRY; DENSE; RED-ORANGE (COASTAL SEDIMENT)  SAND-MEDIUM; DRY; FIRM; TAN- WHITE (COASTAL)  CLAY-STIFF, MCIST, GREY AND SAND-FIRM; TAN INTERBEDDED IN 1° TO 5° LAYERS	5 5 5 5 5 20	3 3 5		7-11- 7-10- 8-16-	-23 -15 7 -20	16" 16"	SEIVE TEST BENTONITE SEAL— HYDROMETER TEST W=14.3%	SOLIO PYC RISER
50 " 54333" 00 00 00 00 00			30 55 40	7 8 9 9		24-32 18-26- 16-23	-29 -18	18"	seive test	

SHEET X UP C

ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONITEAL CIRILE SUITE A TUCKER, GEORGIA 30084 604 - 308-0802 FAX 308-8602

LOG OF BORING

BORING NO. B-1 CONTRACTED WITH U.S. ARMY CERL DATE: 06/13/94 JOB NO.: \_\_JOO148 PROJECT NAME: LAND FARM PROJECT, FT. BENNING LOCGED BY: POP DRILLER: BAILEY MARD, PIEDMONT ENVIRONMENTAL DRILLING RIG: CME 55 DEPTH FEET SAMPLES NOTES DESCRIPTION ELEY. NO. TYPE BLOWS/6' RECON 50 12 15-15-26 18\* 55 12-17-17 14" TR. CLAY: RED-TAN-WHITE 60 SELVE TEST 17-23-20 18\* SOLID PYC RISER 65 BENTONITE SEAL S.G.=2.7 12-14-20 12" 70 HYDROMETER TEST 19' 5-5-7 16 -75 CLAY & SAND; FIRM; NOIST; TAN S.G.=2.67 w=20.6% (COASTAL) SAND-FINE; DENSE; DRY; TAN-WHITE 17-21-23 1B' 17 80 COASTALI 23-22-2618 18 -85 SEIVE TEST 14\* В 6<del>-6-</del>7 TRACE CLAY; MOIST GROUNDWATER AT 92° 6-14-94 1.D. PYC SLOTTED SCREEN TOP OF SAND PACK 10-13-18 16" WET 95 TOP OF SCREEN SAND PACK 16' 21 6-9-11 SAND-TRICLAY, ORGANIC MATTER 100 22" UD-1 BOTTOM OF SCREEN BORING TERMINATED AT 102" K w = 1.8 x 10 4 cm/sec n=474, S.C.=2.67 105

SHEET 1 OF 2

ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CIRCLE, SLETE A TUCKER, GEORGIA 3008-8002

LOG OF BORING

CONTRACTED WITH U.S. ARMY CERL BORING NO.: B-2 JOB NO.1 \_\_ J00148 DATE: 06/14/94 PROJECT NAME: LAND FARM PROJECT, FT. BENRING LOGGED DY: DLW DRILLER: BAILEY WARD, PIEDWICHT ENVIRONMENTAL DRILLING RIG: CME 55 SAMPLES DEPTH SAMPLES
FEET NO. TYPE BLOWS/6" REDON ELEV. DESCRIPTION NOTES SCIVE TEST SAND-TR. CLAY:MEDIUM:LOOSE:BROWN 1 2-H 12 w=9.2% (FILL) 19-17-16 16" SAND-FINE TO MEDIFIRM TO DENSE: - 5 RED-BROWN (COASTAL) W/T TO 3" CLAY SEAMS 8-13-14 16" 10 SEIVE TEST 8-10-10 18" Б w=4.0% 5 13-17-17 18" 20 Lzs 9-10-K 18" HYDROMETER 6 SOME CLAY w≈16.1% S.G.=2.9% 7-6-9 18\* 30 6-6-4 16" -35 13-7-6 18" 40 TRACE CLAY 10 B-15-10 18° SEIVE TEST . -- 45 ¥=9.6% 11 14-14-23 16" -50 CONTINUED, SHEET 2

SKEET 2 OF 2

ADVANCED ENVIRONMENTAL MANAGEMENT, INC.
1198 MONTREAL CIRCLE SUITE A
11UXER GEORGIA 30084
404 - 908-0809 FAX 908-8802

LOG OF BORING

CONTRACTED WITH: U.S. ARMY CERL BORING NO.: 8-2

PROJECT NAME: LAND FARM PROJECT, FT. RENNING JOB NO.: JODIAN DATE: O6/14/94

DRILLER:	BAILEY WARD, PIEDWONT ENVIRONMENT	AL DRIL	LING		RIG:		55	LOGGED BY: DLW
ELEV.	DESCRIPTION	HITES	NC.	S/ TYPE	MPLES BLOWS	/6' R	80Y	NOTES
		- 50						
-		1					l	
	į	F						
		<u>├</u> 55	12	$\mathbb{N}$	8-10-	9	18*	
•		h 33				- 1		
:	1	F				_	_	
<u>.</u>		-60	13		25-17	-10	12.	
•		L				ļ		
:		H	<u></u>		40 41	-	18*	
<u>-</u>		65	14		18-11-	<del>6</del>	<u>מי</u>	•
4.	CLAY-FIRM; MOIST; GREY (COASTAL)	F				١		
•	CAND TO CLAY, MEDICAL TAN	t	15		5-2-3	ᆉ	15,	SEIVE TEST
-	SAND-TR. CLAY; MEDIUM; TAN; (COASTAL)	70	۳		3-6-3	<del>'</del>	-	w=31.87.
*	_	F						
4	NO 84 4 V	ļ	16		14-10	-5	10"	GROUNDWATER AT 70.5'-E/14/94
-	-NO CLAY	<b>⊢</b> 75	1		1,1,10	-		
		E				- 1		
1 1		F	17		15-32	-22	4ª	SEIVE TEST
-	BORING TERMINATED AT 80'	- BO		Г				w=11.DX
4								
-		الم	1			Ì		
-		85		-	1	ļ		
4						ļ		
•		90	1					
-		F				i		
1		F			ì			
, , , ,   , , , , ] , , , ,		H 95		l				
-		F.						
-		F						
1	İ	F100					ļ	
•		t						
5	1	H					ļ	
_		-105			1			
					1			1
		<u> </u>	1	L.				

SHEFT W C

ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1738 MONTREAL CIRCLE, SLITE A TLEXER, GEORGIA 3008-48102

LOG OF BORING

BORING NO. B-3 CONTRACTED WITH: U.S. ARMY CERL DATE: 06/15/94 JOB NO.: \_\_JD0148 PROJECT NAME: LAND FARM PROJECT, FT. BENNING LOGGED BY: DLW RIG: CME 55 DRILLER: BAILEY WARD, PIEDMONT ENVIRONMENTAL ERILLING DEPTH SAMPLES
FEET NO, TYPE BLOWS/6" REDGY. SAMPLES NOTES ELEV. DESCRIPTION . 0 6-10-12 12" CLAY-V. STIFF; NOTTLED RED-WHITE 4 1 1 HYDROMETER w=23.2% (COASTAL) 14-14-13 16" 1777 SAND-TR. CLAY; FIRM TO DENSE: RED-BROWN (COASTAL) SEIVE TEST 6-10-9 16" 10 w=19.47. 6-11-13 18\* TAN 15 6-18-17 16" 5 **-20** 8-10-10 18\* 25 18-49-49 18\* SEIVE TEST SOME CLAY: VERY DENSE -30 w=6.3% 28-55-49 16" 35 20-13-10 18° 40 Ю 12-16-20 18" - 45 9-11-14 16\* SEIVE TEST SOME CLAY 11 -50 HYDRONETER CONTINUED, SHEET 2

w=17.6%

SHEET 2 OF 2

ADVANCED ENVIRONMENTAL MANAGEMENT, INC.

LOG OF BORING

TTSB MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0509 FAX 908-6502

BORING NO. B-3 CONTRACTED WITH U.S. ARMY CERL DATE: 06/15/94 PROJECT NAME: LAND FARM PROJECT, FT. BENNING \_ 100 BOL\_\_ 1.00 BOL\_ RIG: DMF 55 LOGGED BY: DEW DRILLER- RAILEY WARD PIEDMONT ENVIRONMENTAL DRILLING

DRILLER:	BAILEY WARD, PIEDMONT ENVIRONMENT				_RIG:			LOGGED BY: DLW
ELEV.	DESCRIPTION	DEPTH FEET	NO.	S. TYPE	BLOWS	5/6' R	800Y	NOTES
بعلييدا	DENSE, RED-BROWN	50 111155	12	_	22-23	3-19	16ª	
****	FIRM; TAN	-60 -	13	Z	14-12	-16	18°	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		65	14	/	10-9-	-10	16"	
<u> </u>	5" CLAY LAYER, MOIST	70	15	Z	9-9-	12	14*	HYDROMETER w=30.1%
****		-75 -75	16	2	15-10	)-11	12*	
1117		80	17	2	12-7-	9	18*	
7 / 7	SOME CLAY; DENSE; WET	85	18.	2	29-25	5-21	10°	SEIVE TEST w=18.1%
	₹	-90 -1	19	2	19-22	2-20	6"	GROUNDWATER AT 88.5' AT BORING COMPLETION
11111	BORING TERMINATED AT 95'	95	20	2	4-9-1	0	5*	
1   1111		100						
		lui l						

SHEET\_1\_OF

ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA SOSA 404 - 908-0809 FAX 308-8802

LOG OF BORING

BORING NO .: B-4 CONTRACTED WITH: U.S. ARMY CERL JOB NO.: \_\_\_\_J00148 DATE: 06/14/94 PROJECT NAME: LAND FARM PROJECT, FT. BENNING LOGGED BY: DLW DRILLER: BAILEY WARD, PIEDMONT ENVIRONMENTAL DRILLING RIG: CME 55 DEPTH SAMPLES
FEET NO. TYPE BLOWS/6" RECOV. SAMPLES NOTES ELEY. DESCRIPTION SAND-TR. CLAY: MEDIUM: LOOSE TO DENSE; TAN, RED-BROWN (COASTAL) 1-2-7 12" 6-14-13 18\* 2 5 10-13-17 16" 10 CLAY-V. STIFF: RED-BROWN-CREY 9-11-13 18" 15 18-24-19 12" -20 SAND-FINE TO MEDIUM; FIRM; GREY; 6 6-7-7 16" 25 SEIVE TEST 7-10-9 14" WHITE, PINK 30 w=8.6% 9-13-13 18" 8 TAN -35 9 6-9-11 18" 7-9-7 18" SEIVE TEST 10 SOME CLAY 45 HYDROMETER S.G.=2.75 w=10.3% NO CLAY 14-14-8 16" 11 CONTINUED, SHEET 2

SHEET 2 OF 2

ADVANCED ENVIRONMENTAL MANAGEMENT, INC., 1798 MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0808 FAX 808-8802

LOG OF BORING

CONTRACTED WITH: U.S. ARMY CERL BORING NO.: B-4

PROJECT NAME: LAND FARM PROJECT, FT. BENNING JOB NO.: JOSEPH DATE: 06/14/94

ORILLER:	BAILEY WARD, PIEDMONT ENVIRONMENT	AL DRIL	LING		RIG:_			LOGGED BY: DLW
ELEV.	DESCRIPTION	DEPTH FEET	Nn.	TYPE	HPLES BLOWS	/6"	AUUA A	NOTES
			100	1112	BEGING	-		
	TR. CLAY	50 55	12	/	<del>9-9-</del>	10	18ª	
	CLAY-SOME SAND: Y. STIFF; GREYE WHITE (COASTAL)	60	13	2	6- <del>9</del> -	12	18*	SEIVE TEST HYDROMETER W=35X
	SAND-TRACE CLAY: FINE: FIRM: WET: TAN (COASTAL) BORING TERMINATED AT 65'	65	14	2	5-5-	10	16"	GROUNDWATER AT 58' AT BORING COMPLETION
**   ****		70						
_		-75 -75						
,,,,,,,,,,		180						
.		85						
		-30						
11111		95						
1 = = = =		1111105						
		_ N3						

## **Appendix M: Geologic Description of Borings**

Samples described by Marilyn Weiss, October 1994
Color Descriptions from Geological Society of America Rock-Color Chart, 1963. All depths refer to depth below surface.

BORING 1 (MW-1)				
Bed #	Depth	Sample No.	Description	
1	Surface	1	Clayey sand, light brown (5 YR 5/6), fine grained, subangular quartz, micaceous, some white material (possibly gypsum)	
2	5 ft	2	Sand, grayish orange (10 YR 7/4), medium to fine grained, subangular to sub-rounded quartz, micaceous, slightly carbonaceous, come clay aggregates.	
3	10 ft	3	1 inch clay layer variegated in color greenish gray (5 GY 6/1), dark yellowish orange (10 YR 6/6), and dark reddish brown (10 R 3/4), micaceous.	
			Clayey sand, light brown (5 YR 5/6), medium to fine grained, subangular quartz, micaceous	
		4	1 inch of clay layer, light greenish gray (5 GY 8/1), banded by dark reddish brown (10 R 3/4), micaceous	
	15 ft		Sand, moderate brown (10 YR4/4), medium grained subangular quartz, micaceous, small ferruginous clay nodules.	
4	15 ft	5	Clayey sand, grayish orange (10 YR 7/4), medium to fine grained, subangular to subrounded quartz, micaceous	
		6	Clayey sand, very pale orange (10 YR 8/2), minimally mottled with moderate brown (5 YR 4/4) and dark yellowish orange (10 YR 6/6) fine grained, subrounded quartz, small pieces of mica.	
		7	Clayey sand, dark yellowish orange (10 YR 6/6) minimally mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica	
		8	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR 8/2) and moderate brown (5 YR 4/4) fine grained, subrounded quartz, small pieces of mica.	
	35 ft		Narrow layer of clay, less than one-half inch, light olive gray (5 Y 6/1).	
5	40 ft	9	Sand, very pale orange (10 YR 8/2), fined grained, subangular, quartz, large pieces of mica, small clay aggregates comprising less than 2 percent	

	BORING 1 (MW-1) continued				
Bed #	Depth	Sample No.	Description		
6	45 ft	10	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, clay ferruginous nodules of darker color moderate brown (5 YR 3/4), some mica.		
		11	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.		
	55 ft	12	Clayey sand, mostly moderate brown (5 YR 4/4) mottled with dark yellowish orange (10 YR 6/6) and the darker moderate brown (5 YR 3/4), fine grained, subrounded quartz, clay ferruginous nodules of the darker colors, some mica.		
7	60 ft	13	Sand, grayish orange (10 YR 7/4), medium to coarse grained, poorly sorted, subangular quartz, micaceous, small darker aggregates of quartz, clay, and mica		
8	65 ft	14	Clayey sand, heavily mottled with moderate reddish orange (10 R 6/6), moderate red (5 R 4/6), dark yellowish orange (10 YR 6/6), moderate brown (5 YR 4/4), and very pale orange (10 YR 8/2), medium to fine grained subangular quartz, micaceous, ferruginous clay nodules of darker colors.		
·		15	Clayey sand, mostly dark reddish brown (10 R 3/4) mottled with moderate reddish brown (10 R 4/6), moderate reddish orange (10 R 6/6) and traces of dark yellowish orange (10 YR 6/6) medium to fine grained, subangular quartz, ferruginous clay nodules of darker colors.		
		16	Sandy clay, light brown (5 YR 5/6), medium to fine grained subangular quartz, micaceous, clay aggregates.		
		17	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.		
	85 ft	18	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4), fine grained, subrounded quartz, small pieces of mica.		
9	90 ft	19	Sand, grayish orange (10 YR 7/4), coarse to fine grained, subangular to subrounded quartz, micaceous, poorly sorted, some small clay aggregates.		
10	95 ft	20	Clayey sand, dark yellowish orange (10 YR 6/6), fine grained, subrounded quartz, micaceous.		
11	100 ft	21	Silty sand, mottled light gray (N 7) and medium dark gray (N 4), very fine grained, quartz, micaceous, with large pieces approximately 1 to 2 cm in length of organic matter (carbonize).		

BORING #2 (BH-2)			
Bed #	Depth	Sample No.	Description
1	Surface	1	Sand, white (N 9), subangular quartz, medium to fine grained, some small clay aggregates.
2	5 ft	2	Sandy clay, moderate reddish brown (10 R 4/6), with mottlings of dark yellowish orange (10 YR 6/6) and moderate brown (5 YR 4/4), medium to fine grained, subangular quartz, ferruginous, micaceous
3	10 ft	3	1 inch clay layer variegated in color greenish gray (5 GY 6/1), dark yellowish orange (10 YR 6/6) and dark reddish brown (10 R 3/4), micaceous.  Clayey sand, dark yellowish orange (10 YR 6/6) and heavily mottled with moderate brown (5 YR 4/4), very pale orange (10 YR 8/2), and some pale reddish brown (10 R 5/4), medium to fine grained subangular quartz, micaceous, some clay aggregates of darker colors.
4	15 ft	4	Sand, white (N 9), fined grained, subangular, quartz, very micaceous, some clay aggregates and quartz darker in color comprising less than 2 percent.
5	20 ft	5	Sand, pale red (10 R 6/2), medium grained subangular quartz, micaceous, some small clay aggregates.
6	25 ft	6	Clayey sand, grayish red (5 R 4/2) mixture of ferruginous clay nodules of very dusky red purple (5 RP 2/2) surrounded by a mixture of grayish red purple (5 RP 4/2) and dark yellowish orange (10 YR 6/6) medium grained subrounded quartz.
7	30 ft	7	Clayey sand to sandy clay, dark yellowish orange (10 YR 6/6), clay layers of greenish gray (5 GY 6/1), variegated with dark yellowish orange (10 YR 6/6), fine grained, subrounded quartz, small pieces of mica.
		8	Clayey sand to sandy clay, light brown (5 YR 5/6), fine grained quartz, micaceous.
	40 ft	9	Clayey sand to sandy clay, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4), fine grained, subrounded quartz, small pieces of mica.
8	45 ft	10	Sand, white (N 9), medium grained, subangular, quartz, micaceous, some clay aggregates darker in color and comprising less than 2 percent.
9	50 ft	11	Clayey sand to sandy clay, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4), fine grained, subrounded quartz, small pieces of mica.
		12	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.
		13	Clayey sand, very pale orange (10 YR 8/2), mottled with moderate brown (5 YR 4/4) and dark yellowish orange (10 YR 6/6) fine grained, subrounded quartz, small pieces of mica.

BORING #2 (BH-2) continued			
Bed #	Depth	Sample No.	Description
9 cont'd	65 ft	14	Clayey sand to sandy clay, light brown (5 YR 5/6) mottled with dark yellowish orange (10 YR 6/6) and moderate brown (5 YR 3/4), 2 inch layer of clay, medium grained quartz, micaceous, some clay aggregates darker in color.
10	70 ft	15	Sand light brown (5 YR 5/6) medium to coarse grained subangular quartz, small clay aggregates darker in color, micaceous.
11	75 ft	16	Clayey sand, dark yellowish orange (10 YR 6/6) medium to coarse grained subangular quartz, some clay aggregates.
12	80 ft	17	Sand, white (N 9), coarse to medium grained subangular to subrounded quartz, small clay aggregates of darker color.


	BORING #3 (BH-3)				
Bed #	Depth	pth Sample No. Description			
1	Surface	1	Clay, micaceous, variegated greenish gray (5 GY 6/1) with light brown (5 YR 5/6), with some dark reddish brown (10 R 3/4), micaceous, some quartz		
2	5 ft	2	Sand, grayish orange (10 YR 7/4), medium to very fine grained, subangular to sub-rounded quartz, micaceous, some small clay aggregates darker in color.		
3	10 ft	3	Sand, very pale orange (10 YR 8/2), medium to fined grained, poorly sorted, subangular, quartz, very micaceous with some large pieces of mica, some clay aggregates darker in color and comprising less than 2 percent		
4	15 ft	4	Clayey sand, pale red (10 R 6/2), fine grained to very fine grained, subangular to subrounded quartz, micaceous		
	20 ft	5	Clayey sand, pale red (10 R 6/2), fine to very fine grained, subangular to subrounded quartz, micaceous, with clay nodules of grayish red purple (5 RP 4/2).		
5	25 ft	6	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.		
6	30 ft	7	Clayey sand, pale red (10 R 6/2), fine grained, subangular quartz, micaceous, clay aggregates in darker colors.		


BORING #3 (BH-3) continued				
Bed # Depth Sample No. Description				
7 35 ft 8			Clayey sand, light brown (5 YR 5/6) with mottlings of moderate red (5 R 4/6), dark yellowish orange (10 YR 6/6), and moderate brown (5 YR 4/4), fine grained, subrounded quartz, small pieces of mica.	
		9	Clayey sand, mostly moderate brown (5 YR 3/4) with mottling of light moderate brown (5 YR 4/4), fine grained, subrounded quartz, ferruginous, small pieces of mica.	
	45 ft	10	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.	
8	50 ft	11	Sand, dark yellowish orange (10 YR 6/6), medium to fine grained, poorly sorted, subrounded to subangular quartz, micaceous, clay aggregates of 1 to 2 mm in size.	
9	55 ft	12	Clayey sand, moderate reddish brown (10 R 4/6), fine grained, subangular quartz, ferruginous, small pieces of mica.	
YR8/2) and moderate pieces of mica.  14 Clayey sand, dark yelle		13	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.	
		14	Clayey sand, dark yellowish orange (10 YR 6/6), mottled with very pale orange (10 YR8/2) and moderate brown (5 YR4/4) fine grained, subrounded quartz, small pieces of mica.	
		15	Clayey sand to sandy clay, light brown (5 YR 5/6) mottled with dark yellowish orange (10 YR 6/6) and moderate brown (5 YR 3/4), 2 inch layer of clay, medium grained quartz, micaceous, some small clay aggregates of darker colors.	
	cont'd	16	Clayey sand, light brown (5 YR 5/6).fine grained quartz, micaceous, ferruginous.	
10	80 ft	17	Clayey sand to sandy clay, dark yellowish orange (10 YR 6/6) mottled with light brown (5 YR 5/6) and moderate brown (5 YR 4/4), fine grained quartz, clay aggregates, some small pieces of mica.	
11	85 ft	18	Sand, very pale orange (10 YR 8/2), fined grained, subangular, quartz, large pieces of mica, small clay aggregates of darker colors comprising less than 2 percent	
5/6) with mottlings of very pale orange (10 YR 8/2) and dark yel		Clayey sand, small layer of grayish red purple (5 RP 4/2) mostly light brown (5 YR 5/6) with mottlings of very pale orange (10 YR 8/2) and dark yellowish orange (10 YR 6/6), fine grained, subangular to subrounded quartz, micaceous		
	95 ft	20	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) and moderate brown (5 YR 4/4), fine grained, subrounded quartz.	

BORING #4 (BH-4)					
Bed #	Bed # Depth Sample No. Description				
1	Surface	1	Sandy clay, moderate brown (5 YR 4/4), subrounded quartz, fine grained.		
		2	Sandy clay, moderate brown (5 YR 4/4), with striations of greenish gray (5 GY 6/1), subrounded quartz, fine grained.		
		3	Sandy clay, moderate brown (5 YR 4/4), with striations of greenish gray (5 GY 6/1), subrounded quartz, fine grained.		
	15	4	Clay, very light gray (N 8) with dark yellowish orange (10 YR 6/6) striations with moderate brown (5 YR 4/4) clayey sand fine grained, subangular to subrounded quartz, micaceous.		
3	20 ft	5	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) and moderate brown (5 YR 4/4), fine grained, subrounded quartz.		
	25 ft	6	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) and moderate brown (5 YR 4/4), fine grained, subrounded quartz.		
4	30 ft	7	Sand, white (N 9), fine grained, subangular, quartz, very micaceous.		
5	35 ft	8	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) moderate brown (5 YR 4/4), and some moderate reddish brown (10 R 4/6) fine grained, subrounded quartz.		
	40 ft	9	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) and moderate brown (5 YR 4/4), fine grained, subrounded quartz.		
6	45 ft	10	Sand, very pale orange (10 YR 8/2), medium grained, subangular quartz, micaceous, small clay aggregates.		
7	50 ft	11	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) and moderate brown (5 YR 4/4), fine grained, subrounded quartz.		
	55 ft	12	Clayey sand, dark yellowish orange (10 YR 6/6) mottled with very pale orange (10 YR 8/2) moderate brown (5 YR 4/4), and some moderate reddish brown (10 R 4/6) fine grained, subrounded quartz, small pieces of mica		
8	60 ft	13	Sand, light brown (5 YR 6/4) poorly sorted, coarse to medium grained subangular to subrounded quartz, micaceous, clay aggregates.		
9	65 ft	14	Clay, mottled dark yellowish orange (10 YR 6/6) with greenish gray (5 GY 6/1), micaceous.		

### **Appendix N: Grain Size Analysis**

#### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CIRCLE SUITE A TUCKER, GEORGIA 30084 404 - 908-0809 FAX 908-8802







PERCENT PASSING	<b>14</b> 100 %	SOIL DESCRIPTION:	SAND
	*10 100	USCS CLASS:	SP
	*40	SOIL ORIGINA	COASTAL SEDIMENT
	#60 <u>215</u>	SOIL COLOR:	RED-ORANGE
	*100 7.4	SPECIFIC GRAVITY:	
	#200 Q.5	MEDIAN SIZE (DSD)	0.21 NM

### GRAIN SIZE CURVE

LAB TECH: JERRY JOHNSON CHECKED BY: PLET DEP	EPREE, P.E.
--	-------------

### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1738 MONTREAL DIRCLE, SUITE A TUCKER, GEORGIA 300844 404 - 908-0803 FAX 908-8802






SOIL DESCRIPTION:	SAND-CLAYEY	
USCS CLASS:	SC	_
SOIL ORIGIN:	COASTAL SEDIMENT	
SOIL COLOR:	TAN	
SPECIFIC GRAVITY:	2.9	
MEDIAN SIZE (D50)	N/A	


### GRAIN SIZE CURVE

HYDRONETER ONLY

I AR TOML	JERRY JOHNSON	PLECYCH RV.	PIET DEPREE, P.E.

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC., 1798 MONTHEAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0809 FAX 908-8802







### GRAIN SIZE CURVE

LAR TECH	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
1 AR IP H	AFTELL ADDITIONAL	LITELINEU UIII .	

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTHEAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0809 FAX 108-8802







PERCENT PASSING:	*4 100 Z	SOIL DESCRIPTION:	SAND-TRACE CLAY
	*10 99.2	USCS CLASS:	SP
	<b>140 60.4</b>	SOIL ORIGIN	COASTAL SEDIMENT
	*60 27.7	SOIL COLOR:	RED-TAN-WHITE
	*100 8.5	SPECIFIC GRAVITY:	
	*200 12	MEDIAN SIZE (050)	0.35 MM

### GRAIN SIZE CURVE

LAR TECH	JERRY JOHNSON	CHECKER RY:	PLET DEPREE, P.E.

#### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CIRCLE, SUITE A TUCKER, CEORGIA 3008-8 404 - 308-8639 FAX 308-8802







### GRAIN SIZE CURVE

HYDROMETER ONLY

LAB TEC	JERRY	JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
---------	-------	---------	-------------	-------------------

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTHEAL CIRCLE SUITE A TUCKER, GEORGIA 30084 404 - \$08-0809 FAX \$08-8802






PERCENT PASSING: *	A 100 Z	SOIL DESCRIPTION:	SAND-TRACE CLAY
	10 99.4	USCS CLASS:	SP
		SOIL ORIGIN:	COASTAL SEDIMENT
	40		TAN-WHITE
	60	SOIL COLOR:	TOWN HILLE
	100	SPECIFIC GRAVITY:	0.35 MM
	200 2.0	MEDIAN SIZE (D50)	UJJ MM

### GRAIN SIZE CURVE

LAB TECH	JERRY JOHNSON	CHECKED BY: .	PIET DEPREE, P.E.

#### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0809 FAX 308-8802

CONTRACTED WITH	U.S. ARMY CERL		SAMPLE   D = R-7, S-1
PROJECT NAME:	FT. BENNING LANDFARM	JOB NO.:J00148	DATE: 6/20/94




### GRAIN SIZE CURVE

AL I	TECH	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
œ	1		GILLIGHT BILL	

### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1738 MONTREAL GROLE SUITE A TUCKER, GEORGIA 300844 404 - 808-8809 FAX 908-8802






PERCENT PASSING	<b>100 %</b>	SOIL DESCRIPTION:	SAND-SOME CLAY
I DUDIT I FORM	<b>100</b>	USCS CLASS:	sc
	<b>40 94.7</b>	SOIL ORIGINA	COASTAL SEDIMENT
	•60 <u>54.5</u>	SOIL COLOR:	RED-BROWN
	*10027.4	SPECIFIC GRAVITY:	
	*200 <u>18.7</u>	MEDIAN SIZE (D50)	0.14 NM

### GRAIN SIZE CURVE

LAB TECH JERRY JOHNSON CHECKED BY: PIET DEPREE, P.E.
--

# ADVANCED ENVIRÓNMENTAL MANAGEMENT, INC., 1798 MONTREAL CIRCLE SUITE A TUCKER, GEORGÍA 30084 404 - 908-0809 FAX 908-0802

CONTRACTED WITH	U.S. ARMY CERL			SAMPLE I.D. B-2.5-6	
PROJECT NAME:	FT. BENNING LANDFARM	JOB NO.	J00148	DATE: 6/20/94	




SOIL DESCRIPTION:	SAND-SONE CLAY		
USCS CLASS:	SC		
SOIL ORIGIN:	COASTAL SEDIMENT		
SOIL COLOR:	WHITE-GREY		
SPECIFIC GRAVITY:	2.9		
MEDIAN SIZE (D50)	N/A		


### GRAIN SIZE CURVE

HYDROMETER ONLY

LAB	TECH	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
-----	------	---------------	-------------	-------------------

## ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1738 MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA 30014 404 - 108-0109 FAX 908-0802







PERCENT PASSING:	e4 100 Z	SOIL DESCRIPTION:	SAND
1 Electr 1 Aconomic	*10 <u>100</u>	USCS CLASS:	SP
	<b>40 43.8</b>	SOIL ORIGIN	COASTAL SEDIMENT
	*60 7.8	SOIL COLOR:	RED-BROWN
	*100 2.1	SPECIFIC GRAVITY:	
	*200 Q.4	MEDIAN SIZE (DSD)	0.4! NM

### GRAIN SIZE CURVE

1 40	TECH	JERRY JOHNSON	CHECKED BY: _	PIET DEPREE, P.E.
	1 CLUTE			

## ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1758 MONTREAL DROLE SLITE A TUCKER, CEORGIA 300848 404 - 908-0809 FAX 908-8802







PERCENT PASSING	e4 <u>100 %</u>	SOIL DESCRIPTION	SAND-TRACE CLAY
	*10 99.0	USCS CLASS:	SP
	*40 78.7	SOIL ORIGINE	COASTAL SEDIMENT
	*60 39.6	SOIL COLOR:	TAN
	*100 10.4	SPECIFIC GRAVITY:	
	*200 2.5	MEDIAN SIZE (050)	0.3 MM

### GRAIN SIZE CURVE

LAB TECH	JERRY JOHNSON	CHECKED BY:	PLET DEPREE, P.E.

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC., 1738 MONTHEAL DIRCLE, SUITE A TUCKER, GENEGIA 30084 404 - 908-0809 FAX 908-8802






PERCENT PASSING: #4 100 %	SOIL DESCRIPTION	SAND
*1099.7	USCS CLASS:	SP
•40 <u>34.1</u>	SDIL ORIGINA	COASTAL SEDIMENT
*60	SOIL COLOR:	TAN
*100 8.24	SPECIFIC GRAVITY:	
*200 Q.5	MEDIAN SIZE (D50) _	OL48 MM

### GRAIN SIZE CURVE

LAB TECH	JERRY JOHNSON	CHECKED BY:	PLET DEPREE, P.E.

### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1736 MONTREAL CRICLE SUITE A TUCKER, GEORGIA 3008-6 802

CONTRACTED WITH	U.S. ARMY CERL		SANPLE LD	B-3. S-1
PROJECT NAME:	FT. BENNING LANDFARM	JOB NO.: J00148	DATE:	6/20/94



SOIL DESCRIPTION:	<u>CLAY-SANDY</u>
USCS CLASS:	<u> </u>
SOIL ORIGIN:	COASTAL SEDIMENT
SOIL COLOR:	RED-WHITE MOTTLED
SPECIFIC GRAVITY:	2.7
MEDIAN SIZE (DSO)	N/A


### GRAIN SIZE CURVE

HYDRONETER ONLY

LAB TECH:	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
-----------	---------------	-------------	-------------------

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1758 MONTREAL CIRCLE, SUITE A 1TUCKER, GEORGIA 30084 404 - 908-0809 FAX 908-8802







PERCENT PASSING:	*4 100 %	SOIL DESCRIPTION:	SAND-TRACE CLAY
	*10 99.8	USCS CLASS:	SP
	*40 87.1	SOIL ORIGINE	COASTAL SEDIMENT
	*60 37.2	SOIL COLOR:	RED-BROWN
	*100	SPECIFIC GRAVITY:	
	*200 2.7	MEDIAN SIZE (D50)	0.28 MM

### GRAIN SIZE CURVE

LAB TE	壮 .	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0809 FAX 908-8802







PERCENT PASSING: #4 99.8%	SOIL DESCRIPTION:	SAND-SOME, CLAY
*10 <u>99.0</u>	USCS CLASS:	<u> </u>
*40 <u>89.7</u>	SOIL ORIGIN:	COASTAL SEDIMENT
*60 <u>52.1</u>	SOIL COLOR:	TAN
<b>#100</b> <u>314</u>	SPECIFIC GRAVITY:	
<b>■</b> 200 <u>25.7</u>	MEDIAN SIZE (D50)	0.28 MM

### GRAIN SIZE CURVE

LAB	TECH	JERRY JUHNSON	CHECKED BY:	MEI DEPREE, P.E.

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1198 MONTHEAL GROLE SUITE A 110CHER, GEORGIA 30084 404 - 908-0809 FAX 908-6802





PERCENT PASSING:	<b>98.5</b> %	SOIL DESCRIPTION:	SAND-SONE CLAY
10000111000100	*10 94.1	USCS CLASS:	SC
	#40 <u>7f.5</u>	SOIL ORIGINA	COASTAL SEDIMENT
	*60 49.3	SOIL COLOR:	TAN
	*100 <u>37.4</u>	SPECIFIC GRAVITY:	2.7
	07.7	MEDIAN SIZE (DSO)	0.25 <b>1.0.1</b>
	*200 <u>21.1</u>	WEDING OFF BOOK	


### GRAIN SIZE CURVE

WITH HYDROMETER

LAB TECH:	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
-----------	---------------	-------------	-------------------

#### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1738 MONTREAL CIRCLE, SUITE A TUCKER, GEORGIA 30084 404 - 908-0829 FAX 908-6802

CONTRACTED WITH	U.S. ARMY CERL		SAMPLE LD.: B-3. S-15
PROJECT NAMES	FT. BENNING LANDFARM	JOB NO.1J00148	DATE: 6/20/94




SOIL DESCRIPTION:	SAND-SOME CLAY	
USCS CLASS:	SC	
SOIL ORIGIN:	COASTAL SEDIMENT	
SOIL COLOR:	WHITE-GREY	
SPECIFIC GRAVITY:	2.9	
MEDIAN SIZE (DECO	N/A	


### GRAIN SIZE CURVE

HYDROMETER ONLY

LAR TECH	JERRY JOHNSON	CHECKED RY:	MEI DEPREE, P.E.

# ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1738 MONTHEAL CIRCLE SUITE A TUCKER CEORGIA 30084 404 - 908-0809 FAX 908-8802






PERCENT PASSING:		SOIL DESCRIPTION:	SAND-TRACE CLAY SP
	*10 <u>99.9</u> *40 <u>90.3</u>	SOIL ORIGIN	COASTAL SEDIMENT
	*60 <u>75.4</u>	SOIL COLOR: SPECIFIC GRAVITY:	RED-BROWN
	*100 <u>44.0</u> *200 <u>22.1</u>	MEDIAN SIZE (D50)	0.17 NM

### GRAIN SIZE CURVE

LAB TECH	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
LAB TECH	JERNI JUHNJON	CHECKED III.	

## ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1798 MONTFELL CIRCLE, SUITE A 1TUCKER, GEORGIA 30084 404 - 908-0808 FAX 908-8802


CONTRACTED WITH	U.S. ARMY CERL		SAMPLE I.D.i.	B-4. S-7
PROJECT NAME:	FT. BENNING LANDFARM	JOB_NO.:J0014	18 DATE:	6/20/94




### GRAIN SIZE CURVE

	JERRY JOHNSON	CHECKED BY:	PIET DEPREE, P.E.
I AR TECH	OCIALL COMPONE		

## ADVANCED ENVIRONMENTAL MANAGEMENT, INC. 1739 MONTREAL CHOILE, SILITE A 11LCLET, CEORGIA 3008-8 404 - 908-0803 FAX 308-8802






PERCENT PASSING	99.9%	SOIL DESCRIPTIONS	SAND-SOME CLAY
1 2.00011 17.2011-05	*10 99.5	USCS CLASS:	SC
	•4053.7	SOIL ORIGINE	COASTAL SEDIMENT
	•60 33.5	SOIL COLORI	TAN-WHITE
	*100 <u>19.1</u>	SPECIFIC GRAVITY:	2.75
	44.5	MEDIAN SIZE (DSD)	0.002 MM
	*200 <u>H-2</u>	MEDIAN SIZE IDSUI	


### GRAIN SIZE CURVE

WITH HYDROMETER.

			PIET DEPREE, P.E.
	JERRY JOHNSON	CHECKED BY:	(IE) DEFECTAL FALA
LAR TECH	OFIG(1 AQUIDOM	CHECKED BILL	

#### ADVANCED ENVIRONMENTAL MANAGEMENT, INC. TYSE MONTREAL CIRCLE SUITE A TUCKER, GEORGIA 30084 404 - 908-0809 FAX 908-8802





0.002 MM 67.7 MEDIAN SIZE (D50) **200**.


### GRAIN SIZE CURVE


WITH HYDROMETER

LAB TECH JERRY JOH	INSON CHECKED BY:	PIET DEPREE, P.E.
--------------------	-------------------	-------------------

# **Appendix O: Hydraulic Conductivity Values**

Hydraulic Conductivity Results Utilizing AQUITEST





#### Hydraulic Conductivity Results Utilizing Bouwer and Rice Method (1976)

$$K = \frac{r_c^2 \ln (R_e/r_w)}{2L} \frac{1}{t} \ln \frac{y_o}{y_t}$$
 (5)

where: K = hydraulic conductivity of the aquifer (ft/min)

 $r_c$  = inside radius of the casing = 0.167 ft

R<sub>e</sub> = effective radius over which y is dissipated

 $r_w$  = radial distance between the undisturbed aquifer and

the well center = 0.167 ft

L = height of the screen in the well = 5 ft

y = drawdown at time t (ft)

and:

$$\ln \frac{R_{e}}{r_{w}} = \left[ \frac{1.1}{\ln (H/r_{w})} + \frac{A + B \ln [(D - H)/r_{w}]}{L/r_{w}} \right]^{-1}$$
 (6)

where:  $[(D - H)/r_w] = 6$ 

and constants A and B = 2.5 and 0.75, respectively.

#### Resulting Values for Hydraulic Conductivity of the Watertable Aquifer at the Site

Well Tests	Hydraulic Conductivity (ft/min)
Slug Test (AQUITEST)	2.4 x 10 <sup>-3</sup>
Bail Test (AQUITEST)	1.3 x 10-3
Slug Test (Bouwer and Rice)	1.4 x 10-4
Bail Test (Bouwer and Rice)	5.7 x 10 <sup>-5</sup>
Lab Test	3.5 x 10-4

### **Appendix P: SCS Method of Abstractions**

I. Determination of Soil Group

The hydrologic soil groups as defined by SCS soil scientists are:

- A. (Low run-off potential). Soils having a high infiltration rate even when thoroughly wetted and consisting chiefly of deep, well to excessively drained sands or gravels.
- B. Soils having a moderate infiltration rate when thoroughly wetted and consisting chiefly of moderately deep to deep, moderately well to well drained soils with moderately fine to moderately coarse texture.
- C. Soils having a slow infiltration rate when thoroughly wetted and consisting chiefly of soils with a layer that impedes downward movement of water or soils with moderately fine to fine texture.
- D. (High run-off potential). Soils having a very slow infiltration rate when thoroughly wetted and consisting chiefly of clay soils with a high swelling potential, soils with a permanent high watertable, soils with a claypan or clay layer at or near the surface, and shallow soils over nearly impervious material.

Hydraulic group B and a normal antecedent moisture climate (II) was selected as the best fit for overall characteristic of soil at the study area.

II. Determination of SCS Curve Number for Harps Creek watershed:

Land Use Description	Runoff Curve #	
Water surface of rivers and streams	100	28.7%
Wood or forest land: thin stand, poor cover, no m	nulch 66	15.0%
Wood or forest land: good cover	55	41.3%
Open Spaces, good condition: grass cover on		
75% or more of the area	61	15.0%

Weighted CN Number = (0.287)(100) + (0.15)(66) + (0.413)(55) + (0.15)(61) = 70.47

SCS Method of Abstractions Equations:

$$S = \frac{1000}{CN} - 10 \tag{7}$$

$$Pe = \frac{(P - 0.2S)^2}{P + 0.8S}$$
 (8)

where: S = SCS Curve Number
P = Precipitation

Pe = Direct Runoff

SCS Curve Number for AMC (II) = (1000/70.47) - 10 = 4.19Run-off for 48.8 inches of average rainfall =  $[48.8 - 0.02 (4.19)]^2 / [48.8 + 0.8 (4.19)] = 44.80$  in Infiltration = 48.8 - 44.80 = 4.0 in/yr =  $6 \times 10^{-7}$  ft/min 96 USACERL TR-97/136

# Appendix Q: Statistical Rainfall Intensity Data for Fort Benning

Return Periods	30-Min Rain (in)	30-Min Rate (in/hr)	60-Min Rain (in)	60-Min Rate (in/hr)	2-Hour Rain (in)	2-Hour Rain (in/hr)
1-yr	1.35	2.70	1.72	1.72	2.06	1.03
2-yr	1.56	3.12	1.96	1.96	2.37	1.19
5-yr	1.90	3.80	2.44	2.44	2.94	1.47
10-yr	2.14	4.28	2.72	2.72	3.39	1.70
25-yr	2.40	4.80	3.05	3.05	3.85	1.93
50-yr	2.69	5.38	3.35	3.35	4.25	2.13
100-yr	2.90	5.80	3.72	3.72	4.73	2.37

Return Periods	3-Hour Rain (in)	3-Hour Rate (in/hr)	6-Hour Rain (in)	6-Hour Rate (in/hr)
1-yr	2.19	0.73	2.63	0.44
2-yr	2.62	0.87	2.98	0.50
5-yr	3.29	1.10	3.92	0.65
10-yr	3.73	1.24	4.47	0.75
25-yr	4.27	1.42	5.11	0.85
50-yr	4.71	1.57	5.77	0.96
100-yr	5.23	1.74	6.41	1.07

Return Periods	12-Hour Rain (in)	12-Hour Rate (in/hr)	24-Hour Rain (in)	24-Hour Rate (in/hr)
1-yr	3.00	0.25	3.47	0.15
2-yr	3.71	0.31	4.00	0.17
5-yr	4.60	0.38	5.40	0.23
10-yr	5.36	0.45	6.35	0.27
25-yr	6.17	0.51	7.36	0.31
50-yr	6.89	0.57	7.96	0.33
100-yr	7.68	0.64	8.87	0.37

Source: Hershfield 1961

97

# Appendix R: SCS Rainfall Distribution for 24-Hour Storm

I. Calculation of rainfall distribution of a 24-hr/100-yr storm event in a Type II storm area based on 8.87 total inches of precipitation or an intensity of 0.37 inches/hour (Hershfield 1961).


Hour t	$P_t/P_{24}$	Increment	Precipitation (in)
2	0.022	0.022	0.1951
4	0.048	0.026	0.2306
6	0.08	0.032	0.2838
7	0.098	0.018	0.1597
8	0.12	0.022	0.1951
8.5	0.133	0.013	0.1153
9	0.147	0.014	0.1242
9.5	0.163	0.016	0.1419
9.75	0.172	0.009	0.0798
10	0.181	0.009	0.0798
10.5	0.204	0.023	0.2040
11	0.235	0.031	0.2750
11.5	0.283	0.048	0.4258
11.75	0.357	0.074	0.6564
12	0.663	0.306	2.7142
12.5	0.735	0.072	0.6386
13	0.772	0.037	0.3282
13.5	0.799	0.027	0.2395
14	0.82	0.021	0.1863
16	0.88	0.06	0.5322
20	0.952	0.072	0.6386
24	1.000	0.048	0.4258
1	OTALS	1.000	8.87

II. The resultant rates of recharge for transient simulation:


Stress Period	Rate of Recharge (ft/min)									
(each 240 minutes)	12% Recharge of Precipitation	100% Recharge of Precipitation								
1	1.8 x 10-5	1.48 x 10 <sup>-4</sup>								
2	2.7 x 10-5	2.22 x 10 <sup>-4</sup>								
3	2.01 x 10-4	1.67 x 10 <sup>-3</sup>								
4	8.0 x 10-5	6.68 x 10 <sup>-3</sup>								
5	2.7 x 10-5	2.22 x 10 <sup>-4</sup>								
6	1.8 x 10 <sup>-5</sup>	1.48 x 10 <sup>-4</sup>								

### **Appendix S: Transient Model Results**

Typical Groundwater Flow For Watershed During 100-yr/24-hr Storm Event



### Comparison of Typical Changes in Hydraulic Head and Rainfall During a 100-yr/24-hr Storm Event



**Appendix T: Logging Data** 

1995	<b>Drilling</b>	Logs
エノノン		LUZS

0007040	TED WITH CODDS OF ENGINEERS		BORING NO.: MW-2				
	TED WITH: <u>CORPS OF ENGINEERS</u> NAME: <u>FT. BENNING LAND FARM</u>			J	DB NO.:	951349	9-01-05 DATE: 10/24/95
	KILMAN BROTHERS				TRUCK		LOGGED BY: WKC
DKILLEN:		DEPTH			MPLES		NOTES
ELEV.	DESCRIPTION	FEET	NO.		BLOWS/6'	ÆWY.	NOTES
		-0					
	SAND-SILTY; TRACE MICA; HARD; LIGHT	H			8-12-20	20'	
H	RED-DRANGE (RESIDUAL)	<del> </del>					
t		C	2		10-10-10	19'	
F	-BANDED: WHITE-GRANGE; MEDIUM DENSE	- 5			10 ,0 .0		
ŀ.	DETOL	Ľ					
r L		H					·
H	-TRACE SILT; MEDIUM DENSE; RED	H 10	3	_	14-11-14	22'	
	THACE OLLY MEDICINE DELICION	H					
4		Ľ			i.		
Ľ		<u>C</u>	4	7	13-13-23	20'	
F	-DENSE; DEEP RD/BURGUNDY	<del>-</del> 15	<u> </u>				
t.		Ľ.					
ļ.		H		L.,			
H	-DENSE; LIGHT ORANGE	<u> </u>	5	/	14-17-24	23'	
	-BEHOL CHANCE	4				1 1	
F		<u> </u>					
Ľ	SENCE VELLOW LIGHT OPENCE	T\(\sigma\)	6	1	9-11-21	151	
ļ-	-DENSE; YELLOW-LIGHT ORANGE	-25	۲		3 11 21	1	
H.		Ľ					
F		H		Ļ.,		1.00	
H	THE RESERVE OF THE PROPERTY OF	H <sub>30</sub>	1		15-17-31	16"	
<b>L</b>	-DENSE; DARK YELLOW-LIGHT ORANGE	H 30					
4		Ľ				1	
Ľ	-MEDIUM DENSE; RED-DARK RED	F	8		10-12-14	14'	
<b>-</b>	-MEDIUM DENSE; RED-DARK RED	-35	<del>  •</del>	/	10 12 11	1	POSSIBLE SHALLOW CLAY LAYER
Ľ		Ę					36 AND 39 FT.
		ŀ.	-			101	
H	-SOME SILT; TRACE CLAY; FIRM; BANDED: WHITE-RED-YELLOW	L <sub>40</sub>	9	$\angle$	8-7-10	18'	
L.	WHITE-RED-YELLOW	- "					
H		Ľ				<u> </u>	
111	TRACE OF AN DENCE DANDED, VELLO	<u></u>	10	1/	14-11-20	21"	
<b></b>	-TRACE CLAY; DENSE; BANDED: YELLO' ORANGE	45	<u> </u>				1
1 1 1	OTTEN SE	F			1		
ļ.		<u>L</u>	-	+-	17.6.6	19'	†
Ľ	-SOME SILT; TRACE CLAY; FIRM; BROW MOTTLED: DEEP YELLOW-RED	NF - 50		+-	13-6-8	13.	+
	MOLITER: REEL LEFFOR VER						

CONTRACTED WITH: CORPS OF ENGINEERS 1995 Drilling Logs BORING NO.: MW-2											
PROJEC	T NAME: FT. BENNING LAND FARM				JOB NO.:_	9513	49-01-05 DATE: 10/24/95				
DRILLER	: KILMAN BROTHERS				TRUCK		LOGGED BY: WKC				
ELEV.	LEV. DESCRIPTION			TYP	SAMPLES BLOWS/6	RECOV	NOTES				
	CLAY-TRACE SILT; STIFF; GRAY-YELLOW (RESIDUAL)	0 55	12		5-3-8	23'	SAND ABOVE + OR - CLAY LAYER IN SAND SAMPLE BELOW				
<u>,                                    </u>	-SOME SAND; MEDIUM DENSE; GRAY- YELLOW-RED	50	13	/	8-16-18	24'					
	-SANDY; DENSE; YELLOW-NHITE SAND-SOME CLAY; FIRM; GRAY-YELLOW	65	i4		7-8-9	22'	SOME MAGNESE NODULES				
<u>                                     </u>	CLAY-SOME SAND; HARD; BROWN	70 - 70	15	/	6-18-14	24'					
1	-SANDY; TRACE CLAY; VERY STIFF SAND-COARSE; SOME CLAY; MEDIUM DENSE; YELLOW-WHITE-RED	-75 -75 -1	16		9-12-13	22					
<del>-</del>	-SOME SILT; TRACE CLAY; YELLOW	1 -80 1	17	<b>/</b>			DROPPED SPOON IN BORE HOLE				
1	-MEDIUM DENSE; MOIST; YELLOW	<b>8</b> 5	18		8-8-15	18 <b>°</b>					
<del>-</del> - - -	-SILTY; LOOSE; MOIST; BANDED: YELLOW- RED	90 	19		2-2-3	20'					
+ + + + + + +	BORING TERMINATED AT 94 FEET	- 95 - 1 - 1 				100%	☑ UNDISTURBED SAMPLE  GROUNDWATER ENCOUNTERED AT 83.5 FT. AT TIME OF BORING				

#### 1995 Drilling Logs

CONTRAC	CTED WITH: CORPS OF ENGINEERS						BORING NO.:	MW-3
PROJECT	NAME: FT. BENNING LAND FARM			‹	IOB NO.: _	95134	<u>49-01-05</u> DATE:_	10/23/95
DRILLER:	KILMAN BROTHERS			RIG:	TRUCK		LOGGED BY:_	WKC
ELEV.	DESCRIPTION	DEPTH			AMPLES		NOT	(FS
	Scotta non	FEET	NO.	TYPE	BLOWS/6	RECOV.		
_	CAND LOCK BED BROWN (BEGINIAL)	<del> -</del> 0	<u> </u>	-	677	304		
Ŀ	SAND-LOOSE; RED-BROWN (RESIDUAL)	Ľ		/	5-3-3	20*		
F		H						
H	-SOME CLAY; LOOSE; TAN-ORANGE	⊬ ⊢ 5	2		5-3-4	221		
H		4						
<u>H</u>		Ľ						
F	CONT. OF AN EIGHT BANDED ORANGE	H	3		4-6-8	16"		
	-SOME CLAY; FIRM; BANDED: ORANGE- GRAY	F10	<u> </u>		100			
F	3.241	F I						
		-			7-11-15	201		
Γ,	-MEDILIM DENSE; ORANGE	—I5	4	/	1-11-13	20'		
Ľ		Ľ.						
4		<b> </b> -						
<u> </u>	-DENSE; LIGHT ORANGE	H 20	5_		8-12-21	21"		
4		<b>-</b> [						
		Ľ						
-	-MEDIUM DENSE; YELLOW-WHITE	Η	6		8-11-16	18"		
1	MEDICIN SERIOL LEED WITH	一25 H		_	3 11 13			
<b>-</b>		<b> </b> -						
II		1	7		6-10-13	201		
l T	-TRACE SILT; MEDIUM DENSE; MOIST;	<b>—30</b>	1	_	5-10-13	20		
1 1	RED- LIGHT BROWN	ן ו						
7 7		H						
<del>-</del>	SILT-SOME CLAY: TRACE MICA: LOOSE: GRAY-	۲ ⊢35	8	$\angle$	I-3 <b>-</b> 5	21"		
	SILT-SOME CLAY; TRACE MICA; LOOSE; GRAY- YELLOW-RED-ORANGE	н 🔻				ļ		
TT		- -						
-	SAND-YERY DENSE; WHITE-TAN	40	9		13-26-27	17"		
1 1		-40 +						
-		-						
<b>-</b>	COME OF AN EIGH MELLOW WHITE	[	10		3-5-6	19"		
-	-SOME CLAY; FIRM; YELLOW-WHITE	45	_10_		330	-13		
7		<b>-</b>						
- - -		<u> </u>						
		<u> </u>						
i		l i		ŀ			j	

#### 1995 Drilling Logs


CTED WITH: <u>CORPS OF ENGINEERS</u> T NAME: <u>FT. BENNING LAND FARM</u>	10B NO.:	9513	BORING NO.: <u>MW-3</u> 49-01-05 DATE: 10/24/95			
DRILLER: KILMAN BROTHERS						LOGGED BY: WKC
					RECOY	NOTES
				BEVIIO/ G		
-SILTY; SOME CLAY; LOOSE; ORANG-	50	11		3-3-3	24'	
-DENSE; BANDED: YELLOW-LIGHT BROWN- RED; MOTTLED: GRAY	_ 55 	12	/	9-13-17	20'	
-SOME CLAY; MEDIUM DENSE; BANDED: YELLOW-DARK RED	1 60	13	/	4-9-13	24'	
CLAY-SOME SAND; STIFF; WET; TAN-	65	14	/	2-3-12	24"	
	70					
BORING TERMINATED AT 74 FEET	- 75 - 75 - 75				60%	UNDISTURBED SAMPLE  GROUNDWATER ENCOUNTERED AT  64.3 FT. AT TIME OF BORING
	11111					
	7 7 7 7 7 7 7					
	DESCRIPTION  -SILTY; SOME CLAY; LOOSE; ORANGDENSE; BANDED: YELLOW-LIGHT BROWN-RED; MOTTLED: GRAY  -SOME CLAY; MEDIUM DENSE; BANDED: YELLOW-DARK RED  CLAY-SOME SAND; STIFF; WET; TAN-YELLOW	DESCRIPTION  DESCRIPTION  -SILTY; SOME CLAY; LOOSE; ORANG 50  -DENSE; BANDED: YELLOW-LIGHT BROWN- RED; MOTTLED: GRAY  -SOME CLAY; MEDIUM DENSE; BANDED: YELLOW-DARK RED  CLAY-SOME SAND; STIFF; WET; TAN- YELLOW  - 65	DESCRIPTION  DESCRIPTION  DEPTH FEET NO.  -SILTY; SOME CLAY; LOOSE; ORANG-  DENSE; BANDED: YELLOW-LIGHT BROWN- RED; MOTTLED: GRAY  -SOME CLAY; MEDIUM DENSE; BANDED: YELLOW-DARK RED  CLAY-SOME SAND; STIFF; WET; TAN- YELLOW  13  -65	DESCRIPTION  DESCRIPTION  DEPTH S NO. TYPE  -SILTY; SOME CLAY; LOOSE; ORANG-  -DENSE; BANDED: YELLOW-LIGHT BROWN- RED; MOTTLED: GRAY  -SOME CLAY; MEDIUM DENSE; BANDED: YELLOW-DARK RED  CLAY-SOME SAND; STIFF; WET; TAN- YELLOW  -70	DESCRIPTION  DESCR	DESCRIPTION  DESCRIPTION  DESCRIPTION  DESCRIPTION  DEPTH SAMPLES FEET NO. TYPE BLOWS/6' RECOVER


#### 1995 Drilling Logs


CONTRACTED WITH: <u>CORPS OF ENGINEERS</u> <u>B</u> ORING NO.: <u>MW-4</u>									
PROJECT	NAME: FT. BENNING LAND FARM	OB NO.:_	95134	<u>9-01-05</u> DATE:	10/25/95				
DRILLER:	KILMAN BROTHERS			RIG: _	TRUCK		LOGGED BY:	WKC	
5,54	DESCRIPTION	DEPTH			MPLES		NO	IEC	
ELEY.	DESCRIPTION	FEET	NO.	TYPE	BLOWS/6	RECOV.	110		
	TOPSOIL 6-IN.	<u> </u>							
F	SAND-SILTY; SOME CLAY; LOOSE; ORANGE-	4			3-3-3	22'			
<b>-</b>	BROWN (RESIDUAL)	<b>H</b> .							
H		<b>-</b>	2		3-5-7	16'			
<u> </u>	-SOME SILT; FIRM; MOTTLED: ORANGE- ORANGE-YELLOW	<del>-</del> 5			3.3.1	10			
<del>-</del>	GRANGE TELEON	Ľ							
r L		Ç							
<u> </u>	-TRACE CLAY; FIRM; ORANGE-YELLOW	۲.,	3		5-7-7	20'			
	TRACE CLAT; FIRM; GRANGE TELEON	<u></u> 10							
[.		H							
H		<u>ተ</u> .		L-,	7 4 5	-			
Ľ	-TRACE CLAY; LOOSE; BANDED: DARK	L <sub>15</sub>	4	/	3-4-5	22'			
4	ORANGE-RED-WHITE-YELLOW	H							
ł.		<u>+</u>							
Ę		H	5	1	9-7-6	18'			
-	-TRACE CLAY; FIRM; MOTTLED: DARK RED-	-20	۲		3 1 0	1.0			
Ľ	ORANISH		Ì						
ļ.		H		L.,		$oxed{oxed}$			
H	-LOOSE TO FIRM; YELLOW-ORANGE	H - 25	6		3-5-5	20"			
F		- 23							
+		t							
		Ę.	7	1	8-5-5	20"			
	-COARSE; LOOSE; BANDED; ORANGE- YELLOW-BURGUNDY	<b></b>	<del>                                     </del>		0 0 0	+=			
է		Ľ							
F		H						!	
<u> </u>	-COARSE; FIRM; BANDED: WHITE-YELLOW-	H 35	8		10-6-5	20*			
L.	RED	٠, ٢,							
H		1			<u> </u>				
			9	1	6-4-4	22"	SAND IN FIRST I	2 IN OF SAMPLE	
Ė	-SOME CLAY; FIRM; YELLOW-GRAY	<b>—40</b>	-		7 7	126	SAND IN I NOT	2 114 01 3881 11	
į.		Ľ							
<u></u>		H		_	<u> </u>				
4	-COARSE; LOOSE; ORANGE-RED	45	10		7-5-5	22			
-		- 45 -			[				
H		H							
	-COARCE, COME CLAV-LOOSE, ORANGE-	Ľ	<b> </b>	T	8-5-4	20	ţ		
<u> </u>	-COARSE; SOME CLAY; LOOSE; ORANGE- RED	-50	"	1	0-3-4	120	1		
1		1	<u>1</u>	1	<u> </u>		L		

#### 1995 Drilling Logs


	CTED WITH: <u>Corps of Engineers</u>						BORING NO.: MW-4	
	T NAME: FT. BENNING LAND FARM	<del></del>			JOB NO.:	9513	<u> 149-01-05</u> DATE: <u>10/24/95</u>	_
DRILLER	R: KILMAN BROTHERS			_RiG:	TRUCK		LOGGED BY: WKC	
ELEV.	DESCRIPTION	DEPT			SAMPLES		NOTES	-
		FEET	NO	. 1146	E BLOWS/6	RECON	iio ico	
		<del> </del> 0	-		<del> </del>	-		
F		Ľ						
1771	COARCE FIRM WHITE VELLOW	ŀ					]	
$\vdash$	-COARSE; FIRM; WHITE-YELLOW	F 55	12		5-6-7	18'		
111		H. 33						
Ę.		Ľ						
_	-COARSE; LOOSE; WHITE-YELLOW	۲,	13		2-3-3	181	6 IN SANDY CLAY LAYER IN MIDDL	F
F	Sortion, 2000L, Hillie Teleon	-60				<b>-</b>	OF SAMPLE.	
L		ŀ.						
F	CLAY-SANDY; VERY STIFF	F	14	+	10-5-16	20*	MAIGT CAMPA OF IN THE TOTAL IN	
	SAND-VERY COARSE; MEDIUM DENSE;	-65	17		10 5 10	120	MOIST SANDY CLAY IN TOP 10 IN. OF SAMPLE.	
-	WHITE-YELLOW	<b>Ģ</b> .						
<del>1</del>	TRACE OF T. COARCE, MEDITIA DENCE	7 1	-	<b> </b>	10 10 10	201		
_	-TRACE SILT; COARSE; MEDIUM DENSE; MOIST; ORANGE	<del>-</del> 70	15		10-12-12	22"		
4		<b>T</b>						
-1	SILT-SANDY; STIFF; MOIST; YELLOW-WHITE	<b>-</b> 1	<u> </u>	ļ,				
	SILI SANDI; SIEF; MOISI; IELLON-RIIIE	<del>-</del> 75	16	/	4-5-7	24'		
- -	<del>≚</del> [	- <del>-</del>						-
-	_CANDY, CTIFF, WET, DANDED WELLOW	<b>-</b> i						
<del>1</del>	-SANDY; STIFF; WET; BANDED; YELLOW- GRAY-ORANGE	80 80	17		6-6-7	18*		
1	ŀ	4						
;		- -						1
<u>.</u>	BODING TERMINATER AT RA FEET	٠,					X UNDISTURBED SAMPLE	
4	BORING TERMINATED AT 84 FEET	<b>−8</b> 5						
.	į	1					GROUNWATER ENCOUNTERED AT 76 FT. AT TIME OF BORING	
.	F	.					TO THAT TIME OF BUTHING	
-	ţ	-						
	ŀ	.						
	F	;						
-	<u> </u>	-						
	F					1		
	t							
-	-	-						
			İ					
		1	. [	- 1	i	i		1











Lugging Dam






















### **Appendix U: Clay Layer**



USACERL TR-97/136 119

# Appendix V: FEMWATER and LEWASTE Grid



The grid has been expanded by a factor of 10 in the z-direction.



## Appendix W: Assumptions for Program Without Clay Liner

#### Femwater Assumptions:

- 1. Linear matrix equation solution indicator is solved by direct Gaussian elimination
- 2. material type = sand

```
porosity = 0.3
```

xx-component of saturated hydraulic conductivity tensor =  $5.8 \times 10^{-3}$  cm/s zz-component of the saturated hydraulic conductivity tnesor =  $5.8 \times 10^{-3}$  cm/s yy-component of the saturated hydraulic conductivity tensor = 0 cm/s

- 3. Density of water = 1.0
- 4. Acceleration of gravity =  $cm/s^2$
- 5. Dynamic vicosity of wate = 0.013
- 6. Number of nodal points =2520
- 7. Number of elements =2420
- 8. Number of elements in the x-direction = 55
- 9. Number of elements in the z-direction = 44
- 10. Rainfall =  $9.433 \times 10^{-7}$  cm/s
- No ponding is allowed
- 12. Number of Dirichlet nodal points (Discharge Nodes) = 7
- 13. Dirichlet-Head discharge values = 548.64 cm (18 ft)

#### Lewaste

- 1. Transient state
- 2. Distribution coefficient =  $1.0 \times 10^{-2}$
- 3. Bulk density = 1.75
- 4. Longitudinal dispersivity 2.13 x 10<sup>4</sup>
- 5. Lateral dispersivity =  $4.27 \times 10^2$

# Appendix X: Assumptions for Program With Clay Liner

#### Femwater

- Material type = clay liner
   porosity = 0.45
   xx-component of the saturated hydraulic conductivity tensor = 9.00 x 10<sup>-8</sup> cm/s
   zz-component of the saturated hydraulic conductivity tensor = 9.00 x 10<sup>-8</sup> cm/s
   yy-component of the saturated hydraulic conductivity tensor = 0 cm/s
- 2. Material type = clay layer


  porosity = 0.45

  xx-component of the saturated hydraulic conductivity tensor = 9.00 x 10<sup>-5</sup> cm/s


  zz-component of the saturated hydraulic conductivity tensor = 9.00 x 10<sup>-5</sup> cm/s


  yy-component of the saturated hydraulic conductivity tensor = 0 cm/s

**Appendix Y: LEWASTE Grids.** 




LEWASTE 24C ENLARGED TIME = 28.1 YR







LEWASTE 53C ENLARGED TIME = 28.1 YR



#### **USACERL DISTRIBUTION**

Chief of Engineers

ATTN: CEHEC-IM-LH (2)

ATTN: CEHEC-IM-LP (2)

ATTN: CERD-L

CECPW 22310-3862

ATTN: CECPW-E ATTN: CECPW-FT

ATTN: CECPW-ZC

**US Army Engr District** 

ATTN: Library (40)

US Army Engr Division

ATTN: Library (11)

HQ XVIII Airborne Corps 28307 ATTN: AFZA-DPW-EE

US Army Materiel Command (AMC)

Alexandria, VA 22333-0001

ATTN: AMCEN-F

ATTN: AMXEN-C 61299-7190

Installations: (20)

FORSCOM

Forts Gillem & McPherson 30330

ATTN: FCEN

Installations: (20)

TRADOC

Fort Monroe 23651

ATTN: ATBO-G

Installations: (20)

Fort Belvoir 22060

ATTN: CETEC-IM-T

ATTN: CETEC-ES 22315-3803 ATTN: Water Resources Support Ctr

USA Natick RD&E Center 01760

ATTN: STRNC-DT

ATTN: AMSSC-S-IMI

US Army Materials Tech Lab

ATTN: SLCMT-DPW 02172

HQ USEUCOM 09128 ATTN: ECJ4-EN

**CEWES 39180** 

ATTN: Library

**CECRL 03755** 

ATTN: Library

USA AMCOM

ATTN: Facilities Engr 21719

ATTN: AMSMC-EH 61299

ATTN: Facilities Engr (3) 85613

USAARMC 40121

ATTN: ATZIC-EHA

Fort Leonard Wood 65473

ATTN: ATSE-DAC-LB (3) ATTN: ATZT

ATTN: ATSE-CFLO

ATTN: ATSE-DAC-FL

ATTN: Australian Liaison Office

Military Dist of WASH

Fort McNair

ATTN: ANEN-IS 20319

US EPA, Region V

ATTN: AFRC-ENIL-FE 60561

US Army Environmental Center

ATTN: SFIM-AEC-NR 21010

ATTN: SFIM-AEC-CR 64152 ATTN: SFIM-AEC-SR 30335-6801

ATTN: AFIM-AEC-WR 80022-2108

National Guard Bureau 20310 ATTN: NGB-ARI

US Military Academy 10996

ATTN: MAEN-A

ATTN: Facilities Engineer

ATTN: Geography & Envr Engrg

Naval Facilities Engr Command

ATTN: Facilities Engr Command (8)

ATTN: Engrg Field Divisions (11)

ATTN: Public Works Center (8)

ATTN: Naval Constr Battalion Ctr 93043

ATTN: Naval Facil. Engr. Service Ctr 93043-4328

US Gov't Printing Office 20401

ATTN: Rec Sec/Deposit Sec (2)

Defense Tech Info Center 22060-6218 ATTN: DTIC-O (2)

191

8/97